





report date: 2024-03-28

General information

Make	FORD
Model	FUSION 16V FLAME
Colour	Silver
Year of manufacture	2004
Top speed	104 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/16



Internet history

Entry 1

Date 2021-07-25

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/16



MOT history

MOT expiry date	2024-07-19
MOT pass rate	75 %
MOT passed	18
Failed MOT tests	6
Total advice items	39
Total items failed	18

MOT #24		2023-07-18 14:00
MOT test	number	909311564215
Result		✓ Passed
Next expi	ry date	2024-07-19
Advice	Offside Rear Tyre slightly damaged/cracking or perishing stepping and	cracking (5.2.3 (d) (ii))
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))		
Advice	Stop lamp(s) non-obligatory stop lamp not working high level (4.3.1 (a)	(ii))

MOT #23	2023-07-18 09:20
MOT test i	number 790003129995
Result	X Failed
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Stop lamp(s) non-obligatory stop lamp not working high level (4.3.1 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing stepping and cracking (5.2.3 (d) (ii))
MAJOR the ingress	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents of dirt insecure (6.1.7 (g) (ii))
MAJOR	Headlamp aim projected beam image is obviously incorrect both (4.1.2 (c))

MOT #22	2022-07-20 14:24
MOT test number	249012475011
Result	✓ Passed

CarCheck.co.uk page 3/16



MOT #21 2022-07-19 09:27

MOT test number 102095169038

Result X Failed

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))

MAJOR Nearside Headlamp insecure (4.1.1 (c))

MAJOR Headlamp aim projected beam image is obviously incorrect both (4.1.2 (c))

MAJOR Offside Rear Brake pipe excessively corroded flexi to cylinder (1.1.11 (c))

MOT #20 2021-07-20 11:44

MOT test number 180642736005

Result
✓ Passed

MOT #19 2021-01-04 09:11

MOT test number 582942470616

Advice Offside Rear Brake pipe clips or supports missing, pipe adequately supported (1.1.11 (d) (i))

Advice Offside Rear Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Emissions erratic when engine is idling - ok at test speeds though

Advice Brake hose has slight corrosion to ferrule all 4 hoses rusted (1.1.12 (f) (i))

Advice Nearside Rear Brake pipe clips or supports missing, pipe adequately supported (1.1.11 (d) (i))

Advice Nearside Rear Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear brake noisy - build up of dust?

Advice Suspension component mounting prescribed area is corroded but not considered excessive

rusting on inner rear of both sills (5.3.6 (a) (i))

CarCheck.co.uk page 4/16



Result

NH04BJE

report date: 2024-03-28

Passed

MOT #18 2020-01-17 17:36

MOT test number 367075845986

Advice Brake pipe corroded, covered in grease or other material both front to rears (1.1.11 (c))

MOT #17 2019-01-05 11:07

MOT test number 760945382794

Official Deep Deep principle and account in process of the process

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Brake pipe corroded, covered in grease or other material Both brake pipes to wheel cylinders (1.1.11 (c))

MOT #16 2018-01-04 09:25

MOT test number 825187581177

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Exhaust system corroded but still gas tight

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #15 2017-01-21 12:03

MOT test number 180993097183

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

CarCheck.co.uk page 5/16



report date: 2024-03-28

MOT #14

MOT test number

155226121577

Result

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #13 2016-05-21 11:00 **MOT** test number 711522527927 Result × Failed Fail Nearside Front coil spring broken (2.4.C.1a) **Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c) **Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Fail Nearside Headlamp aim too low (1.8) Windscreen wiper does not clear the windscreen effectively Both (8.2.2) Fail Fail Offside Front coil spring broken (2.4.C.1a) **Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Fail Front front brake excessively fluctuating (3.7.B.3) Fail Offside Headlamp aim too low (1.8)

MOT #12	2015-02-18 10:12
MOT test number	227379045050
Result	✓ Passed
Notice Surface rust on brake pipes	

CarCheck.co.uk page 6/16



Fail

NH04BJE

report date: 2024-03-28

MOT #11 2015-02-18 10:12 816319445074 **MOT** test number Result × Failed Pass with rectification Offside Stop lamp adversely affected by the operation of another lamp (1.2.1f) Pass with rectification Offside Headlamp aim too high (1.8) **Pass with rectification** Nearside Stop lamp not working (1.2.1b) Pass with rectification Nearside Headlamp aim too high (1.8) **Notice** Surface rust on brake pipes

 MOT #10
 2013-09-02 16:36

 MOT test number
 708395843247

 Result
 ✓ Passed

MOT #9

MOT test number

Result

Result

Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

CarCheck.co.uk page 7/16



MOT #8 2013-07-12 08:32

MOT test number 237653693109

Result X Failed

Fail Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #7 2012-06-13 11:02

MOT test number 917805762139

Result
✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #6 2011-05-27 15:17

MOT test number 445577741165

Result
✓ Passed

MOT #5 2010-05-20 11:26

MOT test number 982200240180

Result \(\sqrt{Passed} \)

MOT #4 2009-05-29 15:01

MOT test number 143119149119

Result ✓ Passed

CarCheck.co.uk page 8/16



MOT #3	2008-07-07 10:08
MOT test number	893159488191
Result	✓ Passed
MOT #2	2007-07-16 14:56
MOT test number	270337197126
Result	✓ Passed
MOT #1	2007-05-18 13:04
MOT test number	202668337182
Result	✓ Passed

CarCheck.co.uk page 9/16



Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	19 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 10/16



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-28

Owner history

o mer metery	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	

THE STREET STREET	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	OK NE
Plate since	
	More info >

CarCheck.co.uk page 13/16



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 14/16



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-07-06
Last registration	2023-07-18
Complete history	See info



Registration #1	2004-07-06	8 mi
Registration #2	2007-05-18	26.864 mi
Registration #3	2007-07-16	28.607 mi
Registration #4	2008-07-07	33.217 mi
Registration #5	2009-05-29	38.020 mi
Registration #6	2010-05-20	40.600 mi
Registration #7	2011-05-27	42.554 mi
Registration #8	2012-06-13	31.253 mi
Registration #9	2013-07-12	57.526 mi
Registration #10	2013-07-23	57.573 mi
Registration #11	2013-09-02	57.573 mi
Registration #12	2015-02-18	65.531 mi
Registration #13	2016-05-21	65.534 mi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		11.777 es
Registration #25		11.777 es



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
60567	
60569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1468 mm
Length	3917 mm
Wheel base	2486 mm
Kerb weight	1075 kg
Max. allowed weight	1520 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 16,