



YXIIIXLF

report date: 2024-03-29

General information

Make	MINI
Model	MINI (R57) COOPER D
Colour	White
Year of manufacture	2011
Top speed	121 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	76.4 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-12-05
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-09
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	4
Total items failed	3

MOT #14	2023-10-21 12:03
MOT test number	651960748031
Result	✓ Passed
Next expiry date	2024-11-09

MOT #13	2022-10-21 06:54
MOT test number	932587676197
Result	✓ Passed

MOT #12	2021-11-10 12:39
MOT test number	400457687856
Result	✓ Passed

MOT #11	2020-10-12 11:34
MOT test number	437428050681
Result	✓ Passed

Advice Engine covers and under trays fitted covering certain testable items

MOT #10	2019-10-15 15:31
MOT test number	257243020513
Result	✓ Passed

**MOT #9** 2019-10-15 13:54**MOT test number** 699533605064**Result** ✗ Failed

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm outer and inner edge (5.2.3 (e))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm outer and inner edge (5.2.3 (e))

MAJOR Front Windscreen wiper does not clear the windscreen effectively both sides (3.4 (b) (ii))

MOT #8 2019-04-27 08:54**MOT test number** 651597969988**Result** ✓ Passed**MOT #7** 2018-04-19 13:08**MOT test number** 814058911926**Result** ✓ Passed**MOT #6** 2017-04-24 13:45**MOT test number** 634131209559**Result** ✓ Passed**MOT #5** 2017-04-24 08:39**MOT test number** 800699887678**Result** ✗ Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm tyre wall scrubbed (4.1.E.1)

MOT #4 2016-04-08 10:02**MOT test number** 620669891241**Result** ✓ Passed



MOT #3	2015-03-25 15:49
MOT test number	436834285050
Result	✓ Passed

MOT #2	2015-03-25 11:21
MOT test number	917794685004
Result	✗ Failed
<div><div>Fail</div> Front Windscreen wiper does not clear the windscreen effectively (8.2.2)</div> <div><div>Fail</div> Front registration plate deteriorated (6.3.1d)</div>	

MOT #1	2014-03-24 16:17
MOT test number	545373984095
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
9 November 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	9 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	YX11XLF
Plate since	2019-09-29
Current registration	YX11XLF
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-30
Last registration	2023-10-21
Complete history	See info



Registration #1	2011-03-30	16 mi
Registration #2	2014-03-24	51.981 mi
Registration #3	2015-03-25	72.756 mi
Registration #4	2015-03-25	72.756 mi
Registration #5	2016-04-08	80.356 mi
Registration #6	2017-04-24	86.955 mi
Registration #7	2017-04-24	86.957 mi
Registration #8	2018-04-19	92.878 mi
Registration #9	2019-05-20	95.277 mi
Registration #10	2019-05-20	95.277 mi
Registration #11	2019-05-20	95.277 mi
Registration #12	2019-05-20	95.277 mi
Registration #13	2019-05-20	95.277 mi
Registration #14	2019-05-20	95.277 mi
Registration #15	2019-05-20	95.277 mi
Registration #16	2019-05-20	95.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1200 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	70577801