





report date: 2024-03-29

# General information

Make	HYUNDAI
Model	I20 MPI GO
Colour	White
Year of manufacture	2016
Top speed	106 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	83 BHP
Max. torque	122 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	68.9 mpg
Consumption combined	58.9 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/11



# Internet history


#### Entry 1


Date 2021-01-31


Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



M	$OT^-$	history
- 141	$\circ$	IIISLUIV

MOT expiry date	2024-12-09
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	2
Total items failed	2

MOT #7	2023-11-23 11:10
MOT test number	678699524765
Result	✓ Passed
Next expiry date	2024-12-09

MOT #6	2022-12-02 10:56
MOT test number	348554921821
Result	<b>√</b> Passed

MOT #5	2021-11-22 10:45
MOT test number	875732493279
Result	✓ Passed
Advice Nearside Rear Nail in tyre	

MOT #4	2020-12-10 08:48
MOT test number	727629976980
Result	✓ Passed

MOT #3	2020-06-26 08:49
MOT test number	685233443994
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



SJ16BJG

report date: 2024-03-29

 MOT #2
 2019-07-02 07:40

 MOT test number
 224891135715

 Result
 ✓ Passed

 MOT #1
 2019-06-21 11:57

 MOT test number
 812526564889

 Result
 X Failed

**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Fail Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**Advice** Nearside Rear Puncture repair carried out just above sidewall

CarCheck.co.uk page 4/11



# Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	9 December 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



# Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
THE PARTY OF THE P	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-06-30
Last registration	2023-11-23
Complete history	See info



Registration #1	2016-06-30	20 mi
Registration #2	2019-06-21	18.205 mi
Registration #3	2019-07-02	18.491 mi
Registration #4	2020-06-26	22.925 mi
Registration #5	2020-12-10	24.773 mi
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	85%
Children	73%
Pedestrian	79%
Safety systems	64%
Overall rating	77%
Video	see crash video



# Dimensions & weight

Width	1734 mm
Height	1474 mm
Length	4035 mm
Wheel base	2570 mm
Kerb weight	1158 kg
Max. allowed weight	1580 kg

#### Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/

Number of axles 2

**Engine number** G4LAGM952964