





report date: 2024-03-28

#### General information

Maka	DENALUE
Make	RENAULT
Model	CAPTUR DYNAMIQUE S NAV TCE
Colour	Red
Year of manufacture	2018
Top speed	106 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	90 BHP
Max. torque	140 Nm at 2.250 rpm
Engine capacity	898 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

#### Entry 2

Date	2021-10-27

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-10-26
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/11



RX18LWS
report date: 2024-03-28

MOT history

MOT expiry date	2025-04-29
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	8
Total items failed	2

MOT #5	2024-04-22 10:43
MOT test number	244714907893
Result	✓ Passed
Next expiry date	2025-04-29

MOT #4		2023-04-25 08:48
MOT test	number	469010734512
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2.4mm (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2.9mm (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #3	2022-04-21 10:00
MOT test	number 615564109780
Result	✓ Passed
Advice	Offside Front Brake pad(s) wearing thin 70% worn and discs are lipped (1.1.13 (a) (ii))
Advice Nearside Front Brake pad(s) wearing thin 70% worn and discs are lipped (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



**Pass with rectification** 

RX18LWS

report date: 2024-03-28

MOT test number

526645420732

Result

Pass with rectification
Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice
Offside Front Brake pad(s) wearing thin 70% worn and discs are lipped (1.1.13 (a) (ii))

Advice
Nearside Front Brake pad(s) wearing thin 70% worn and discs are lipped (1.1.13 (a) (ii))

MOT #1 2021-04-15 10:28
MOT test number 950793198511
Result ✓ Passed

Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	29 April 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

_	
Owner	hictory
OWITEL	HIISLULV

For how long did the current and previous owner(s) have this RENAULT? How many owne have? Check it in the premium report and see all owner registrations. Download the full re		AULT
***************************************		
THE PARTY OF THE P		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		
Current registration	NK NA	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-04-30
Last registration	2024-04-22
Complete history	See info



Registration #1	2018-04-30	28 mi
Registration #2	2021-04-15	22.397 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Adult	88%
Children	79%
Pedestrian	61%
Safety systems	81%
Overall rating	80%
Video	see crash video



## Dimensions & weight

Width	1778 mm
Height	1566 mm
Length	4122 mm
Wheel base	2606 mm
Kerb weight	1109 kg
Max. allowed weight	1682 kg

## Additional information

Fuel tank capacity	45
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11