



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VERSO VVT-I SR
Colour	Silver
Year of manufacture	2008
Top speed	121 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	127 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	36.7 mpg
CO2 emission	184 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-06-30
Pictures	4
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-06
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	29
Total items failed	11

MOT #18	2023-09-25 09:21
MOT test number	739557491619
Result	✓ Passed
Next expiry date	2024-10-06
<div>Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))</div> <div>Minor Offside Front Position lamp has a product on the lens or light source which obviously reduces light intensity (4.2.3 (b) (i))</div> <div>Advice Nearside Front Tyre worn close to legal limit/worn on edge Close to limit. (5.2.3 (e))</div> <div>Minor Nearside Front Position lamp has a product on the lens or light source which obviously reduces light intensity (4.2.3 (b) (i))</div> <div>Advice Offside Rear Outer Tyre slightly damaged/cracking or perishing Outer wall cracking slightly. (5.2.3 (d) (ii))</div>	

**MOT #17**

2022-10-05 11:25

**MOT test number**

892472378233

**Result**

✓ Passed

- Advice** Parking brake lever defective but can be satisfactorily operated Lever travel reserve (1.1.6 (d))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened on both sides (1.1.14 (a) (ii))
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced on both sides (6.1.1 (c) (i))
- Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords wall (5.2.3 (d) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened on both sides (1.1.14 (a) (ii))
- Minor** Front Anti-roll bar ball joint dust cover severely deteriorated on both sides (5.3.4 (b) (i))
- Advice** Rear Inner sills corrosion on both sides
- Advice** Front Brake pad(s) wearing thin and pads on both sides (1.1.13 (a) (ii))
- Advice** Offside Front Power steering pump has slight seepage (2.1.5 (a))

**MOT #16**

2021-10-06 10:28

**MOT test number**

542950695380

**Result**

✓ Passed

- Advice** Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
- Advice** Under tray covers fitted
- Advice** Parking brake lever defective but can be satisfactorily operated lever travel reserve (1.1.6 (d))
- Advice** Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))

**MOT #15** 2021-10-06 10:28**MOT test number** 443615117185**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))**Advice** Parking brake lever defective but can be satisfactorily operated lever travel reserve (1.1.6 (d))**Advice** Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))**Advice** Under tray covers fitted**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**MOT #14** 2020-10-07 11:27**MOT test number** 262262828824**Result** ✓ Passed**MOT #13** 2019-09-23 11:19**MOT test number** 284743471217**Result** ✓ Passed**MOT #12** 2018-09-21 09:45**MOT test number** 928482269213**Result** ✓ Passed**Advice** Engine undertray insecure

**MOT #11** 2018-09-21 09:45**MOT test number** 132946530793**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Engine undertray insecure**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MOT #10** 2017-10-03 09:18**MOT test number** 893804510943**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**MOT #9** 2017-10-03 09:18**MOT test number** 632424817276**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Nail in tyre**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #8** 2016-10-03 08:28**MOT test number** 310742979622**Result** ✓ Passed**MOT #7** 2016-02-16 10:09**MOT test number** 584943528965**Result** ✓ Passed



<b>MOT #6</b>	2015-03-10 11:56
---------------	------------------

<b>MOT test number</b>	947549965091
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2014-03-19 15:57
---------------	------------------

<b>MOT test number</b>	357038574042
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside Rear Brake pad(s) wearing thin (3.5.1g)
---------------	--

<b>MOT #4</b>	2013-03-22 12:06
---------------	------------------

<b>MOT test number</b>	967881583098
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Notice</b>	Front tyres close to legal limit
---------------	----------------------------------

<b>MOT #3</b>	2012-03-16 10:59
---------------	------------------

<b>MOT test number</b>	166776272046
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2011-03-18 13:25
---------------	------------------

<b>MOT test number</b>	858427171009
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



MOT #1	2011-03-17 12:18
MOT test number	538426471015
Result	✗ Failed
Fail	Nearside Front Headlamp aim too low (1.8)
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Parking brake lever has no reserve travel (3.1.6b)
Fail	Offside Front Headlamp aim too low (1.8)
Pass with rectification	Offside Front Windscreen wiper blade insecure (8.2.2)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
6 October 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	6 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-03-19
Last registration	2023-09-25
Complete history	<a href="#">See info</a>



Registration #1	2008-03-19	25 mi
Registration #2	2011-03-17	27.336 mi
Registration #3	2011-03-18	27.381 mi
Registration #4	2012-03-16	38.036 mi
Registration #5	2013-03-22	48.389 mi
Registration #6	2014-03-19	58.666 mi
Registration #7	2015-03-10	68.337 mi
Registration #8	2016-02-16	74.575 mi
Registration #9	2016-10-03	79.430 mi
Registration #10	2017-10-03	84.664 mi
Registration #11	2018-03-20	89.337 mi
Registration #12	2019-03-20	94.000 mi
Registration #13	2020-03-20	98.663 mi
Registration #14	2021-03-20	103.326 mi
Registration #15	2022-03-20	107.989 mi
Registration #16	2023-03-20	112.652 mi
Registration #17	2024-03-20	117.315 mi
Registration #18	2025-03-20	121.978 mi
Registration #19	2026-03-20	126.641 mi
Registration #20	2027-03-20	131.304 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1620 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	1ZZV035065