



report date: 2024-03-29

General information

Make	FORD
Model	FUSION FUSION +
Colour	Black
Year of manufacture	2006
Top speed	102 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.8 mpg
CO2 emission	149 g/km
CO2 label	F







Internet history

Entry 1

Date	2021-09-27
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-04
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	31
Total items failed	9

MOT #21	2023-10-05 14:39
MOT test number	663472683845
Result	✓ Passed
Next expiry date	2024-10-04

MOT #20	2022-08-31 16:45
MOT test number	507292983766
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))

MOT #19	2021-09-24 11:37
MOT test number	901996557001
Result	✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Minor	Front Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #18** 2020-11-04 17:50**MOT test number** 462288294692**Result** ✓ Passed**MOT #17** 2019-11-05 13:34**MOT test number** 427445041676**Result** ✓ Passed

Advice Headlamp has a product on the lens but not seriously reducing light output Both head lamps.
(4.1.4 (b))

Minor Windscreen damaged but not adversely affecting driver's view Chip in screen. (3.2 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge Thread depth 3mm. (5.2.3 (e))

MOT #16 2019-10-28 16:00**MOT test number** 646943289834**Result** ✗ Failed

MAJOR Offside Rear reflector missing (4.8.2 (a) (ii))

DANGEROUS Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure
Defect also has excessive cracking. Defect also so consists of low thread depth. (5.2.3 (d) (ii))

MAJOR Rear fog lamp not working (4.5.1 (a) (ii))

Advice Headlamp has a product on the lens but not seriously reducing light output Both head lamps.
(4.1.4 (b))

MAJOR Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge Thread depth 3mm. (5.2.3 (e))

Minor Windscreen damaged but not adversely affecting driver's view Chip in screen. (3.2 (a) (i))

MAJOR Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Pass with rectification Windscreen washer provides insufficient washer liquid Loose pipe. (3.5 (a))

**MOT #15** 2018-10-26 12:01**MOT test number** 464537695371**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2017-10-23 12:37**MOT test number** 649220638488**Result** ✓ Passed**Advice** Offside Front tyre deteriorated**Advice** Nearside Rear tyre deteriorated**MOT #13** 2016-09-12 16:55**MOT test number** 499712062484**Result** ✓ Passed**Advice** Front registration plate faded but not likely to be misread (6.3.1d)**MOT #12** 2016-09-12 16:55**MOT test number** 896039675397**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on main beam (1.7.5a)**Advice** Front registration plate faded but not likely to be misread (6.3.1d)**Pass with rectification** Offside Stop lamp not working (1.2.1b)

**MOT #11** 2015-09-25 13:02**MOT test number** 542516329618**Result** ✓ Passed**Advice** Centre Rear engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)**MOT #10** 2015-03-27 16:35**MOT test number** 295556685087**Result** ✓ Passed**MOT #9** 2015-03-27 14:55**MOT test number** 215976485054**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear reflector missing (1.5.1a)**Fail** Rear fog lamp not working (1.3.2b)**MOT #8** 2014-03-21 17:48**MOT test number** 406210584075**Result** ✓ Passed**MOT #7** 2013-03-25 15:25**MOT test number** 839804583035**Result** ✓ Passed**MOT #6** 2012-03-31 09:44**MOT test number** 669061492047**Result** ✓ Passed**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #5** 2012-03-31 09:44**MOT test number** 406881192027**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**MOT #4** 2011-03-30 13:41**MOT test number** 469829381031**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-04-06 12:45**MOT test number** 653316390037**Result** ✗ Failed**Pass with rectification** Centre Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**MOT #2** 2010-04-06 12:45**MOT test number** 604306390056**Result** ✓ Passed**MOT #1** 2009-05-16 13:43**MOT test number** 433426539168**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
4 October 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	4 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-05-26
Last registration	2023-10-05
Complete history	See info



Registration #1	2006-05-26	29 mi
Registration #2	2009-05-16	9.629 mi
Registration #3	2010-04-06	12.082 mi
Registration #4	2011-03-30	24.247 mi
Registration #5	2012-03-31	35.856 mi
Registration #6	2013-03-25	40.133 mi
Registration #7	2014-03-21	43.617 mi
Registration #8	2015-03-27	46.278 mi
Registration #9	2015-03-27	46.278 mi
Registration #10	2015-09-25	47.250 mi
Registration #11	2016-09-12	49.843 mi
Registration #12	2016-09-12	51.337 mi
Registration #13	2016-09-12	51.337 mi
Registration #14	2016-09-12	51.337 mi
Registration #15	2016-09-12	51.337 mi
Registration #16	2016-09-12	51.337 mi
Registration #17	2016-09-12	51.337 mi
Registration #18	2016-09-12	51.337 mi
Registration #19	2016-09-12	51.337 mi
Registration #20	2016-09-12	51.337 mi
Registration #21	2016-09-12	51.337 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1952 mm
Height	1534 mm
Length	4020 mm
Wheel base	2485 mm
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

6L46495