



report date: 2024-03-28

General information

Make	VOLVO
Model	XC60 D3 SE LUX
Colour	White
Year of manufacture	2012
Top speed	121 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	178 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-01-10
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	16
Total items failed	3

MOT #14	2024-01-08 12:35
MOT test number	738972525934
Result	✓ Passed
Next expiry date	2025-01-10
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))
Advice	Nearside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

MOT #13	2024-01-08 09:21
MOT test number	379521379040
Result	✗ Failed
MAJOR	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Offside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))
Advice	Nearside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #12	2023-01-09 14:28
MOT test number	863666790647
Result	✓ Passed

**MOT #11** 2022-01-11 10:25**MOT test number** 829301187254**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #10** 2020-12-15 09:45**MOT test number** 972567514196**Result** ✓ Passed**MOT #9** 2020-12-14 15:22**MOT test number** 885304750930**Result** ✗ Failed**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8** 2019-12-16 14:25**MOT test number** 616776215537**Result** ✓ Passed**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2018-12-18 15:30**MOT test number** 748748706670**Result** ✓ Passed**MOT #6** 2018-12-18 10:42**MOT test number** 330238688106**Result** ✗ Failed**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #5** 2018-01-02 15:27**MOT test number** 877616966705**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2018-01-02 12:12**MOT test number** 674099365687**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2017-01-04 13:45**MOT test number** 893923017031**Result** ✓ Passed**MOT #2** 2016-01-11 14:31**MOT test number** 355785450624**Result** ✓ Passed**MOT #1** 2015-01-09 15:25**MOT test number** 146359105073**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
10 January 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	10 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-01-10
Last registration	2024-01-08
Complete history	See info



Registration #1	2012-01-10	12 mi
Registration #2	2015-01-09	22.062 mi
Registration #3	2016-01-11	29.423 mi
Registration #4	2017-01-04	35.066 mi
Registration #5	2018-01-02	41.500 mi
Registration #6	2018-01-02	41.501 mi
Registration #7	2018-12-18	47.340 mi
Registration #8	2018-12-18	47.340 mi
Registration #9	2019-01-02	47.340 mi
Registration #10	2019-01-02	47.340 mi
Registration #11	2019-01-02	47.340 mi
Registration #12	2019-01-02	47.340 mi
Registration #13	2019-01-02	47.340 mi
Registration #14	2019-01-02	47.340 mi
Registration #15	2019-01-02	47.340 mi
Registration #16	2019-01-02	47.340 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1808 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	1079629
---------------	---------