



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI
Colour	Blue
Year of manufacture	2008
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Engine capacity	1.986 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-06-06
Pictures	11
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-02-17
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	43
Total items failed	4

MOT #16 2023-02-18 09:04

MOT test number 587960569317

Result ✓ Passed

Next expiry date 2024-02-17

- Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))
- Advice** Front Registration plate insecure but not likely to fall off (0.1 (a))
- Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear both sides (5.3.4 (a) (i))
- Advice** Underside generally corroded
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

MOT #15 2021-10-07 19:24

MOT test number 539572475818

Result ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14**

2021-10-07 19:24

**MOT test number**

756295244301

**Result****✗ Failed****Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Minor**

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Pass with rectification**

Nearside Headlamp aim too high (4.1.2 (a))

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2020-10-23 14:27

**MOT test number**

181730492218

**Result****✓ Passed****Advice**

Offside Front Tyre worn close to legal limit/worn on edge 235/45/17 (5.2.3 (e))

**Minor**

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge 235/45/17 - unevenly on inner edge (5.2.3 (e))

**Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge 235/45/17 - unevenly on inner edge (5.2.3 (e))

**Advice**

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice**

Rear exhaust system corroded

**MOT #12**

2020-10-17 08:22

**MOT test number**

712456741339

**Result****✗ Failed****Advice**

Offside Rear Tyre worn close to legal limit/worn on edge 235/45/17 - unevenly on inner edge (5.2.3 (e))

**Fail**

Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice**

Rear exhaust system corroded

**Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge 235/45/17 - unevenly on inner edge (5.2.3 (e))

**Advice**

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Minor**

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge 235/45/17 (5.2.3 (e))

**MOT #11**

2019-05-31 14:38

**MOT test number**

735574388453

**Result****✓ Passed****MOT #10**

2018-05-30 15:26

**MOT test number**

311255952139

**Result****✓ Passed****Advice**

Front Brake disc worn, pitted or scored, but not seriously weakened x 2 (1.1.14 (a) (ii))

**Advice**

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice**

Rear Brake disc worn, pitted or scored, but not seriously weakened x 2 (1.1.14 (a) (ii))

**MOT #9** 2018-05-30 12:13**MOT test number** 106877809556**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened x 2 (1.1.14 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened x 2 (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MOT #8** 2017-05-22 12:42**MOT test number** 373382500768**Result** ✓ Passed**Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Rear Direction indicator has light sources not illuminating, but not more than 50% (1.4.A.2c)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front brake disc worn, pitted or scored, but not seriously weakened x 2 (3.5.1i)**MOT #7** 2016-05-25 14:40**MOT test number** 263706370190**Result** ✓ Passed**Advice** Nearside Front advise child seats fitted not allowing inspection of belts n/s/f tyre cut in outer wall

**MOT #6** 2016-05-25 08:46**MOT test number** 955044028780**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Front advise child seats fitted not allowing inspection of belts n/s/f tyre cut in outer wall**MOT #5** 2015-04-23 10:08**MOT test number** 476493915185**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-05-07 10:52**MOT test number** 895067224104**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-04-22 11:33**MOT test number** 999342613112**Result** ✓ Passed**MOT #2** 2012-04-27 11:31**MOT test number** 399238212120**Result** ✓ Passed



MOT #1	2011-04-28 10:16
MOT test number	275938011431
Result	✓ Passed





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-04-30
Last registration	2023-02-18
Complete history	<a href="#">See info</a>



Registration #1	2008-04-30	19 mi
Registration #2	2011-04-28	39.531 mi
Registration #3	2012-04-27	54.852 mi
Registration #4	2013-04-22	64.535 mi
Registration #5	2014-05-07	75.719 mi
Registration #6	2015-04-23	83.551 mi
Registration #7	2016-05-25	94.050 mi
Registration #8	2016-05-25	94.050 mi
Registration #9	2017-05-22	108.392 mi
Registration #10	2018-05-22	121.377 mi
Registration #11	2019-05-22	134.362 mi
Registration #12	2020-05-22	147.347 mi
Registration #13	2021-05-22	160.332 mi
Registration #14	2022-05-22	173.317 mi
Registration #15	2023-05-22	186.302 mi
Registration #16	2024-05-22	199.287 mi
Registration #17	2025-05-22	212.272 mi
Registration #18	2026-05-22	225.257 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1510 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

---

**Number of seats**

5

**Engine number**

CBA 067351

---