



PEUGEOT

MIOLJA

report date: 2024-03-29

General information

Make	PEUGEOT
Model	4007 HDI GT
Colour	Green
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	156 BHP
Max. torque	380 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	40.4 mpg



LABEL UNKNOWN

**MOT history**

MOT #17	2023-02-01 09:54
MOT test number	481459856174
Result	✓ Passed
Next expiry date	2024-01-31
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #16	2022-01-22 15:10
MOT test number	678805905208
Result	✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #15	2022-01-20 11:02
MOT test number	652521643222
Result	✗ Failed
MAJOR	Nearside Rear Position lamp not working (4.2.1 (a) (ii))
MAJOR	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
MAJOR	Front Body component damaged and likely to cause injury bonnet emblem (6.2.1 (a) (i))
MAJOR	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
MAJOR	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #14	2021-01-18 17:53
MOT test number	213929122405
Result	✓ Passed
Advice	Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
Advice	Rear exhaust flange rusty
Advice	Offside Rear Tyre worn close to legal limit/worn on edge ON LIMIT (5.2.3 (e))

**MOT #13** 2021-01-18 15:17**MOT test number** 362322020932**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge ON LIMIT (5.2.3 (e))**MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear exhaust flange rusty**MOT #12** 2020-01-21 16:25**MOT test number** 233367130183**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)**Advice** Nearside Front Tyre worn close to legal limit/worn on edge ON LIMIT (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2020-01-21 08:05**MOT test number** 782461226840**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge ON LIMIT (5.2.3 (e))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Play in steering rack inner joint(s)**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2019-01-28 12:52**MOT test number** 427594058305**Result** ✓ Passed

**MOT #9** 2019-01-25 15:07**MOT test number** 762920505099**Result** ✗ Failed**DANGEROUS** Brake disc in such a condition that it is seriously weakened both rear pitted (1.1.14 (a) (ii))**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Offside Steering rack has excessive free play detected at the steering wheel (steering rack fitted) rack end (2.3 (a) (i))**MOT #8** 2018-05-22 09:19**MOT test number** 691109565228**Result** ✓ Passed**MOT #7** 2017-05-24 09:16**MOT test number** 588370744765**Result** ✓ Passed**MOT #6** 2016-05-17 08:16**MOT test number** 451956958558**Result** ✓ Passed



MOT #5	2015-05-14 10:19
MOT test number	535924835183
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4	2014-05-16 12:51
MOT test number	129696934197
Result	✓ Passed

MOT #3	2014-05-16 12:41
MOT test number	775366634128
Result	✗ Failed
Fail	Rear Trailer electrical socket (13 pin) not operating the trailer lamps as intended (1.9.4)

MOT #2	2014-01-15 12:12
MOT test number	447265814065
Result	✓ Passed
Advice	Parking brake lever has little reserve travel (3.1.6b)
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1	2013-01-09 10:39
MOT test number	678949803062
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-01-26
Last registration	2023-02-01
Complete history	See info



Registration #1	2010-01-26	21 mi
Registration #2	2013-01-09	21.786 mi
Registration #3	2014-01-15	26.490 mi
Registration #4	2014-05-16	27.606 mi
Registration #5	2014-05-16	27.606 mi
Registration #6	2015-05-14	35.480 mi
Registration #7	2016-05-17	42.309 mi
Registration #8	2017-05-24	49.762 mi
Registration #9	2018-05-22	55.083 mi
Registration #10	2019-05-22	55.083 mi
Registration #11	2019-05-22	55.083 mi
Registration #12	2019-05-22	55.083 mi
Registration #13	2019-05-22	55.083 mi
Registration #14	2019-05-22	55.083 mi
Registration #15	2019-05-22	55.083 mi
Registration #16	2019-05-22	55.083 mi
Registration #17	2019-05-22	55.083 mi
Registration #18	2019-05-22	55.083 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1805 mm
Height	1670 mm
Length	4635 mm
Wheel base	2672 mm
Max. allowed weight	2410 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number

NOT KNOWN