





report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO ACTIVE SPORT
Colour	Red
Year of manufacture	-
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg



CarCheck.co.uk page 1/11



report date: 2024-03-28


Internet history

Entry 1

Date 2021-06-07


Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT #14 2021-01-20 11:44

MOT test number 137462525166

Result ✓ Passed

Next expiry date 2022-01-19

Advice Exhaust has a minor leak of exhaust gases center to rear joint leaking (6.1.2 (a))

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 47% (1.2.1 (b) (i))

MOT #13 2021-01-15 13:00

MOT test number 430310098330

Result X Failed

DANGEROUS Offside Front Suspension arm likely to become detached (5.3.3 (a) (ii))

MAJOR Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 47% (1.2.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Offside Front Suspension arm corroded and seriously weakened (5.3.3 (b) (i))

Advice Exhaust has a minor leak of exhaust gases center to rear joint leaking (6.1.2 (a))

MOT #12 2019-07-11 11:50

MOT test number 973718002294

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #11 2019-07-11 09:36

MOT test number 536189287850

Result X Failed

MAJOR Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Pass with rectification Nearside Headlamp aim too low (4.1.2 (a))

Advice Oil leak, but not excessive gearbox (8.4.1 (a) (i))

MAJOR Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Pass with rectification Offside Headlamp aim too low (4.1.2 (a))

MOT #10 2018-06-25 13:15

MOT test number 695852626843

Result \(\sqrt{Passed} \)

MOT #9 2018-06-22 10:54

MOT test number 803796004928

Result X Failed

MAJOR Rear fog lamp not working (4.5.1 (a) (ii))

MAJOR Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #8 2017-07-04 09:52

MOT test number 807943207187

Result

Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #7 2016-07-08 09:59

MOT test number 312928610361

Result
✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

MOT #6	2015-07-06 09:22
MOT test number	527267785131
Result	✓ Passed
MOT #5	2013-07-12 14:18
MOT test number	707633093107
Result	✓ Passed
MOT #4	2012-07-13 10:23
MOT test number	875635592167
Result	✓ Passed
MOT #3	2011-07-11 16:42
MOT test number	516822691192
Result	✓ Passed
MOT #2	2010-06-24 09:39
MOT test number	113755470166
Result	✓ Passed
MOT #1	2009-07-01 08:54
MOT test number	723682689111
Result	✓ Passed

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NK NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



PL06BE0 report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-06-30
Last registration	2021-01-20
Complete history	See info



Registration #1	2006-06-30	6 mi
Registration #2	2009-07-01	9.281 mi
Registration #3	2010-06-24	12.494 mi
Registration #4	2011-07-11	14.000 mi
Registration #5	2012-07-13	15.489 mi
Registration #6	2013-07-12	17.962 mi
Registration #7	2015-07-06	20.651 mi
Registration #8	2016-07-08	22.699 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 10/11



PL06BE0 report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	2585 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles2Engine number3265726