



report date: 2024-03-29

General information

Make	MINI
Model	MINI (R60) COOPER SD
Colour	Silver
Year of manufacture	2011
Top speed	123 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	61.4 mpg
CO2 emission	122 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-06-17
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-25
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	65
Total items failed	19

MOT #172024-04-17 15:33

MOT test number140028831980

Result✓ Passed

Next expiry date2025-04-25

- Advice

Offside Rear brake pad warning sensor broken
- Advice

Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16**

2024-04-17 08:02

MOT test number

535407583712

Result**✗ Failed**

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear brake pad warning sensor broken
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #15

2023-04-26 15:20

MOT test number

100793816607

Result**✓ Passed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))



MOT #14	2022-05-30 08:34
MOT test number	875697607247
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front lower ball joint rubber boot slightly deteriorated

MOT #13	2021-05-21 15:38
MOT test number	414460370913
Result	✓ Passed
Advice	Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rearward bush (5.3.4 (a) (i))
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rearward bush (5.3.4 (a) (i))
Advice	Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12**

2021-05-21 10:53

MOT test number

412731003805

Result**✗ Failed**

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rearward bush (5.3.4 (a) (i))
- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rearward bush (5.3.4 (a) (i))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))

MOT #11

2020-05-26 11:15

MOT test number

128987335075

Result**✓ Passed****MOT #10**

2019-10-16 12:11

MOT test number

633030499085

Result**✓ Passed**

- Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**MOT #9**

2019-10-15 09:13

MOT test number

939019364990

Result**✗ Failed**

Fail Offside Rear Inner Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

Fail Nearside Rear Inner Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail Nearside Rear Upper Position lamp light intensity significantly reduced (4.2.3 (a) (ii))

Advice Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge heavily worn inner edge + on wear indicators (5.2.3 (e))

MOT #8

2018-10-13 11:01

MOT test number

506735084640

Result**✓ Passed**

Advice Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Play in steering rack inner joint(s) Both

MOT #7

2018-10-13 08:10

MOT test number

702047309677

Result**✗ Failed**

Advice Offside Rear Nail in tyre

Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

Advice Play in steering rack inner joint(s) Both

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #6** 2017-10-18 11:58**MOT test number** 947175389595**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Service light on**MOT #5** 2017-10-17 10:58**MOT test number** 161419207467**Result** ✗ Failed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Service light on**Fail** Offside Upper Stop lamp not working (1.2.1b)**Advice** Nearside Rear Outer Brake pad(s) wearing thin advise replacement (3.5.1g)**Advice** Offside Rear Nail in tyre**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Offside Upper Rear position lamp(s) not working (1.1.A.3b)**Fail** Offside Rear Inner Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

**MOT #4**

2017-10-14 10:59

MOT test number

422238868773

Result

✗ Failed

- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Nearside Headlamp cleaning device inoperative (1.7.2)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Offside Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Smoke reading 0.0
- Fail** Offside Headlamp cleaning device inoperative (1.7.2)
- Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)

MOT #3

2016-10-12 09:40

MOT test number

734227742491

Result

✓ Passed

- Advice** Rear tyres have uneven wear
- Advice** Offside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Offside Rear Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

MOT #2

2015-10-08 12:47

MOT test number

235783049193

Result

✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit 2.5mm (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit 2.3mm (4.1.E.1)



MOT #1	2014-10-09 11:20
MOT test number	229862384266
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
25 April 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	25 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	WN61PZC
Plate since	2019-09-29
Current registration	WN61PZC
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-10-13
Last registration	2024-04-17
Complete history	See info



Registration #1	2011-10-13	19 mi
Registration #2	2014-10-09	43.501 mi
Registration #3	2015-10-08	54.360 mi
Registration #4	2016-10-12	65.103 mi
Registration #5	2017-10-14	76.054 mi
Registration #6	2017-10-17	76.059 mi
Registration #7	2017-10-18	76.059 mi
Registration #8	2018-10-13	91.087 mi
Registration #9	2018-10-13	91.087 mi
Registration #10	2019-10-15	108.167 mi
Registration #11	2019-10-15	108.167 mi
Registration #12	2019-10-15	108.167 mi
Registration #13	2019-10-15	108.167 mi
Registration #14	2019-10-15	108.167 mi
Registration #15	2019-10-15	108.167 mi
Registration #16	2019-10-15	108.167 mi
Registration #17	2019-10-15	108.167 mi
Registration #18	2019-10-15	108.167 mi
Registration #19	2019-10-15	108.167 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1320 kg
Max. allowed weight	1790 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

74577792