




report date: 2022-07-05

General information

Make	ABARTH
Model	GRANDE PUNTO 155 BHP ABARTH
Colour	White
Year of manufacture	2009
Top speed	129 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Torque	201 Nm at 5.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.5 mpg
Consumption extra urban	44.4 mpg
Consumption combined	34.1 mpg
CO2 emission	162 g/km
CO2 label	G





Internet history

Advert 1

Date	2021-07-18
Pictures	0
Listing price	View report

source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-07-31
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	29
Total items failed	16

MOT #16 2022-08-01 14:13

MOT test number 315467252874

Result ✓ Passed

Next expiry date 2023-07-31

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #15 2022-08-01 08:32

MOT test number 934961121611

Result ✗ Failed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))

MOT #14 2021-02-04 13:08

MOT test number 725350345781

Result ✓ Passed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened front and rear all four (1.1.14 (a) (ii))
- Advice** Front Exhaust has a minor leak of exhaust gases flexie section (6.1.2 (a))



MOT #13 2020-01-22 13:20

MOT test number 294394196250

Result ✔ Passed

- Advice** Rear seat not fully secured.
- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12 2020-01-22 12:46

MOT test number 467070829096

Result ✘ Failed

- Advice** Rear seat not fully secured.
- Fail** Battery insecure and likely to cause a short circuit (4.13 (a) (ii))
- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11 2019-02-04 14:58

MOT test number 590216373075

Result ✔ Passed

- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))



MOT #10	2018-02-02 16:56
MOT test number	553952010194
Result	✓ Passed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #9	2018-02-02 15:24
MOT test number	405192293382
Result	✗ Failed
Fail	Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)
Fail	Offside Front Front position lamp(s) not working (1.1.A.3b)
Fail	Nearside Registration plate lamp not working (1.1.C.1d)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm Tyre at 0mm (4.1.E.1)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm Tyre at 1mm (4.1.E.1)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #8	2017-02-03 10:39
MOT test number	928535821016
Result	✓ Passed
Advice	Offside Rear top side light bulb not working
Advice	Engine cover and under tray fitted obscuring some parts



MOT #7 2017-02-01 17:41

MOT test number 483001445982

Result ✗ Failed

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Rear parking brake recording little or no effort (3.7.B.6a)
- Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Rear Tie bar/rod ball joint dust cover insecure so that it no longer prevents the ingress of dirt Drop link (2.4.G.2)
- Advice** Offside Rear top side light bulb not working
- Advice** Engine cover and under tray fitted obscuring some parts

MOT #6 2016-01-18 15:09

MOT test number 259147030049

Result ✓ Passed

- Advice** Front Tyre worn close to the legal limit both (4.1.E.1)

MOT #5 2015-01-23 08:37

MOT test number 137853125063

Result ✓ Passed

MOT #4 2013-04-18 10:56

MOT test number 826038203138

Result ✓ Passed

- Notice** Under-trays fitted obscuring some underside components



MOT #3	2013-04-12 10:02
MOT test number	389192203188
Result	✗ Failed
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Nearside Front position lamp(s) not working (1.1.A.3b)
Fail	Offside Front coil spring incomplete (2.4.C.1a)
Notice	Under-trays fitted obscuring some underside components

MOT #2	2012-04-25 14:19
MOT test number	318946812169
Result	✓ Passed

MOT #1	2012-04-25 10:16
MOT test number	276596212464
Result	✗ Failed
Fail	Nearside Inner Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2023

✓
MOT
Expires:
31 Juli 2023

Tax status Valid until 1 August

Days left 352

MOT expiry date 31 Juli 2023

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 210,00,-
Single six month payment	£ 110,25,-
Total payable by 12 monthly instalments	£ 220,50,-




Damage history

Check the damage history for this ABARTH. See if, where and when this ABARTH had damage and the car repair costs. We also check if this ABARTH was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra ABARTH salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

Download >



Vehicle valuation

What is this car worth? See the vehicle value of this ABARTH in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

Download >



Owner history

For how long did the current and previous owner(s) have this ABARTH? How many owners did this ABARTH have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

Download >

Plate changes

See in this check if this ABARTH had different number plates.

Number of plates	1
Current registration	WV09ENC
Plate since	2019-09-29
Current registration	WV09ENC
Plate since	2019-09-29

Download >



Finance check

Check if this ABARTH is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this ABARTH has been settled. If not, and you buy this ABARTH then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this ABARTH is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

Download >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-04-24
Last registration	2022-08-01
Complete history	See info



Registration #1	2009-04-24	14 mi
Registration #2	2012-04-25	44.137 mi
Registration #3	2012-04-25	44.137 mi
Registration #4	2013-04-12	56.658 mi
Registration #5	2013-04-18	56.658 mi
Registration #6	2015-01-23	68.429 mi
Registration #7	2016-01-18	77.228 mi
Registration #8	2017-02-01	82.082 mi
Registration #9	2017-02-03	82.806 mi
Registration #10	2019-05-29	95.277 mi
Registration #11	2019-05-29	95.277 mi
Registration #12	2019-05-29	95.277 mi
Registration #13	2019-05-29	95.277 mi
Registration #14	2019-05-29	95.277 mi
Registration #15	2019-05-29	95.277 mi
Registration #16	2019-05-29	95.277 mi
Registration #17	2019-05-29	95.277 mi
Registration #18	2022-08-01	114.277 mi

Download >



Premium report

Get the ABARTH premium report and get full access to more information.

- ✓ Finance check
- ✓ Mileage registrations (18)
- ✓ Damage check
- ✓ Stolen check
- ✓ Car features list
- ✓ Owners history + plate changes

[Download >](#)

Dimensions & weight

Width	1726 mm
Height	1490 mm
Length	4041 mm
Wheel base	2510 mm
Kerb weight	1185 kg
Max. allowed weight	1665 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine code	1348627