



report date: 2022-07-05

General information

Make	ABARTH
Model	GRANDE PUNTO 155 BHP ABARTH
Colour	White
Year of manufacture	2009
Top speed	129 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Max. torque	201 Nm at 5.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	53.3 mpg
Consumption combined	40.9 mpg
CO2 emission	162 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-18
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2024-07-31
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	31
Total items failed	16

MOT #17 2023-07-31 12:27**MOT test number** 855548240852**Result** ✓ Passed**Next expiry date** 2024-07-31**Minor** Steering lock not functioning (7.3 (a))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #16** 2022-08-01 14:13**MOT test number** 315467252874**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #15** 2022-08-01 08:32**MOT test number** 934961121611**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))

**MOT #14**

2021-02-04 13:08

MOT test number

725350345781

Result

✓ Passed

Advice Brake disc worn, pitted or scored, but not seriously weakened front and rear all four (1.1.14 (a) (ii))

Advice Front Exhaust has a minor leak of exhaust gases flexie section (6.1.2 (a))

MOT #13

2020-01-22 13:20

MOT test number

294394196250

Result

✓ Passed

Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Rear seat not fully secured.

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12

2020-01-22 12:46

MOT test number

467070829096

Result

✗ Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Battery insecure and likely to cause a short circuit (4.13 (a) (ii))

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Rear seat not fully secured.

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

**MOT #11** 2019-02-04 14:58**MOT test number** 590216373075**Result** ✓ Passed**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #10** 2018-02-02 16:56**MOT test number** 553952010194**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #9** 2018-02-02 15:24**MOT test number** 405192293382**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm Tyre at 1mm (4.1.E.1)**Fail** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm Tyre at 0mm (4.1.E.1)

**MOT #8** 2017-02-03 10:39**MOT test number** 928535821016**Result** ✓ Passed**Advice** Offside Rear top side light bulb not working**Advice** Engine cover and under tray fitted obscuring some parts**MOT #7** 2017-02-01 17:41**MOT test number** 483001445982**Result** ✗ Failed**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Rear Tie bar/rod ball joint dust cover insecure so that it no longer prevents the ingress of dirt Drop link (2.4.G.2)**Advice** Offside Rear top side light bulb not working**Fail** Rear parking brake recording little or no effort (3.7.B.6a)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Engine cover and under tray fitted obscuring some parts**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #6** 2016-01-18 15:09**MOT test number** 259147030049**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)**MOT #5** 2015-01-23 08:37**MOT test number** 137853125063**Result** ✓ Passed

**MOT #4** 2013-04-18 10:56**MOT test number** 826038203138**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2013-04-12 10:02**MOT test number** 389192203188**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Under-trays fitted obscuring some underside components**Fail** Offside Front coil spring incomplete (2.4.C.1a)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #2** 2012-04-25 14:19**MOT test number** 318946812169**Result** ✓ Passed**MOT #1** 2012-04-25 10:16**MOT test number** 276596212464**Result** ✗ Failed**Fail** Nearside Inner Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✓
MOT

Expires:
31 July 2024

Tax status	Valid until 1 August
Days left	98
MOT expiry date	31 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this ABARTH. See if, where and when this ABARTH had damage and the car repair costs. We also check if this ABARTH was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra ABARTH salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this ABARTH in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this ABARTH? How many owners did this ABARTH have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this ABARTH had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this ABARTH is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this ABARTH has been settled. If not, and you buy this ABARTH then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this ABARTH is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-04-24
Last registration	2023-07-31
Complete history	See info



Registration #1	2009-04-24	14 mi
Registration #2	2012-04-25	44.137 mi
Registration #3	2012-04-25	44.137 mi
Registration #4	2013-04-12	56.658 mi
Registration #5	2013-04-18	56.658 mi
Registration #6	2015-01-23	68.429 mi
Registration #7	2016-01-18	77.228 mi
Registration #8	2017-02-01	82.082 mi
Registration #9	2017-02-03	82.806 mi
Registration #10	2018-02-02	92.456 mi
Registration #11	2019-05-20	101.277 mi
Registration #12	2019-05-20	101.277 mi
Registration #13	2019-05-20	101.277 mi
Registration #14	2019-05-20	101.277 mi
Registration #15	2019-05-20	101.277 mi
Registration #16	2019-05-20	101.277 mi
Registration #17	2019-05-20	101.277 mi
Registration #18	2019-05-20	101.277 mi
Registration #19	2019-05-20	101.277 mi

More info >

**Dimensions & weight**

Width	1726 mm
Height	1490 mm
Length	4041 mm
Wheel base	2510 mm
Kerb weight	1185 kg
Max. allowed weight	1665 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	1348627