



report date: 2024-03-28

General information

Make	VOLVO
Model	V90 D4 INSCRIPTION
Colour	Black
Year of manufacture	2018
Top speed	140 mph
0 - 60 mph	8.2 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-10-01
Pictures	0
Listing price	View report

source: heycar.co.uk



MOT history

MOT expiry date	2024-06-21
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	14
Total items failed	2

MOT #5	2023-06-16 15:47
MOT test number	128521048858
Result	✓ Passed
Next expiry date	2024-06-21
Advice	Offside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))
Advice	Engine covers and under -trays are fitted which may obscure some components

**MOT #4**

2023-06-16 09:54

MOT test number

229963817074

Result**✗ Failed**

- Advice** Engine covers and under -trays are fitted which may obscure some components
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Rear Brake disc worn, but not excessively Both (1.1.14 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin Close to limit (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))
- Advice** Nearside Rear Nail in tyre Not repairable
- Advice** Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))
- Advice** Nearside Front Brake pad(s) wearing thin Close to limit (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))

MOT #3

2022-06-22 10:53

MOT test number

522967385380

Result**✓ Passed**

- Advice** Engine covers and under-trays are fitted which may obscure some components

MOT #2

2021-06-16 08:21

MOT test number

418646848834

Result**✓ Passed**



MOT #1	2021-04-09 16:27
MOT test number	809848457005
Result	✓ Passed
Advice	Trays and covers fitted -- not allowing full inspection of covered areas



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
21 June 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	21 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YR18H NK
Plate since	2019-09-29
Current registration	YR18H NK
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-04-30
Last registration	2023-06-16
Complete history	See info



Registration #1	2018-04-30	26 mi
Registration #2	2021-04-09	32.519 mi
Registration #3	2021-06-16	33.256 mi
Registration #4	2023-06-16	33.256 mi
Registration #5	2023-06-16	33.256 mi
Registration #6	2023-06-16	33.256 mi
Registration #7	2023-06-16	33.256 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	80%
Pedestrian	76%
Safety systems	93%
Overall rating	88%
Video	see crash video



Dimensions & weight

Width	1895 mm
Height	1475 mm
Length	4936 mm
Wheel base	2941 mm
Kerb weight	1696 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2363154