



HONDA



report date: 2024-03-28

General information

Make	HONDA
Model	INSIGHT IMA SE
Colour	Black
Year of manufacture	2010
Top speed	113 mph
0 - 60 mph	12.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	87 BHP
Max. torque	121 Nm at 4.500 rpm
Engine capacity	1.339 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	61.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	101 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-08-15
Pictures	8
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-01
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	19
Total items failed	0

MOT #13	2024-04-02 14:58
MOT test number	408708835696
Result	✓ Passed
Next expiry date	2025-04-01
Advice	Nearside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #12	2023-04-01 09:30
MOT test number	448568252088
Result	✓ Passed
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #11** 2023-03-31 11:12**MOT test number** 707945848763**Result** ✗ Failed

DANGEROUS Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice Central Front Items removed from driver's view prior to test

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Vehicles internal headlight adjuster altered to recheck lights

MOT #10 2021-10-14 07:08**MOT test number** 174948547304**Result** ✓ Passed**MOT #9** 2021-04-06 12:01**MOT test number** 725635927695**Result** ✓ Passed

Advice Items removed from driver's view prior to test

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #8 2020-03-18 17:33**MOT test number** 265671596469**Result** ✓ Passed**MOT #7** 2019-03-05 12:42**MOT test number** 695183924089**Result** ✓ Passed

**MOT #6** 2018-03-08 11:42**MOT test number** 702032147963**Result** ✓ Passed**Advice** Front Both tyre outter side walls perished NO CORDS EXPOSED.**MOT #5** 2017-02-16 11:51**MOT test number** 852268115057**Result** ✓ Passed**Advice** Front Wipers smear windscreen not effecting the drivers view.**MOT #4** 2016-03-03 13:09**MOT test number** 735018928241**Result** ✓ Passed**MOT #3** 2015-03-04 11:19**MOT test number** 156963565440**Result** ✓ Passed**MOT #2** 2014-03-05 12:32**MOT test number** 819514364087**Result** ✓ Passed**MOT #1** 2013-02-19 12:21**MOT test number** 185180253025**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
1 April 2025

Tax status	Valid until 1 October
Days left	156
MOT expiry date	1 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	B
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-15
Last registration	2024-04-02
Complete history	See info



Registration #1	2010-03-15	7 mi
Registration #2	2013-02-19	2.504 mi
Registration #3	2014-03-05	3.288 mi
Registration #4	2015-03-04	4.095 mi
Registration #5	2016-03-03	5.406 mi
Registration #6	2017-02-16	6.380 mi
Registration #7	2018-03-08	8.342 mi
Registration #8	2019-03-05	10.484 mi
Registration #9	2020-03-05	12.504 mi
Registration #10	2021-03-05	14.504 mi
Registration #11	2022-03-05	16.504 mi
Registration #12	2023-03-05	18.504 mi
Registration #13	2024-03-05	20.504 mi
Registration #14	2025-03-05	22.504 mi
Registration #15	2026-03-05	24.504 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	74%
Pedestrian	76%
Safety systems	86%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1425 mm
Length	4396 mm
Wheel base	2550 mm
Kerb weight	1240 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LDA3 1028716