




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOUAREG TDI SE SPORT
Colour	Blue
Year of manufacture	2005
Top speed	111 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	174 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel
Consumption city	20.8 mpg
Consumption extra urban	34.9 mpg
Consumption combined	28.0 mpg
CO2 emission	273 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-06-29
Pictures	11
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-26
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	32
Total items failed	12

MOT #21	2023-07-14 15:07
MOT test number	791160151847
Result	✓ Passed
Next expiry date	2024-07-26
Advice	Underbody tray fitted

MOT #20	2022-07-27 14:07
MOT test number	114863277638
Result	✓ Passed
Advice	Nearside Rear Nail in tyre
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19**

2022-07-22 14:24

**MOT test number**

453828386823

**Result**

✗ Failed

**Minor**

Nearside Rear Tyre obviously under inflated (5.2.3 (l))

**Fail**

Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Fail**

Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**Advice**

Nearside Rear Nail in tyre

**Fail**

Offside Rear Position lamp not working (4.2.1 (a) (ii))

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail**

Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))

**MOT #18**

2021-07-13 18:11

**MOT test number**

146618424767

**Result**

✓ Passed

**Advice**

UNDER TRAY FITTED

**MOT #17**

2021-07-05 13:08

**MOT test number**

566433601983

**Result**

✗ Failed

**Advice**

UNDER TRAY FITTED

**Fail**

Offside Rear Coil spring mounting fractured (5.3.1 (b) (i))

**Fail**

Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Fail**

Rear Brake disc in such a condition that it is seriously weakened BOTH SIDE (1.1.14 (a) (ii))

**MOT #16**

2020-07-08 14:53

**MOT test number**

300093374522

**Result**

✓ Passed

**MOT #15** 2020-06-30 15:05**MOT test number** 538199585304**Result** ✗ Failed**Fail** Nearside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Service brake efficiency below requirements (1.2.2 (a) (i))**MOT #14** 2019-01-31 15:47**MOT test number** 713464876992**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #13** 2018-01-24 10:47**MOT test number** 733983623006**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Parking brake efficiency low (16%)**MOT #12** 2017-01-09 10:12**MOT test number** 377265732385**Result** ✓ Passed**Advice** Handbrake efficiency 16 %**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #11** 2016-01-14 12:28**MOT test number** 382618221513**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #10**

2015-01-27 14:13

**MOT test number**

287717725033

**Result**

✓ Passed

**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9**

2015-01-27 14:13

**MOT test number**

867477125076

**Result**

✗ Failed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #8**

2014-01-08 10:04

**MOT test number**

595468204041

**Result**

✓ Passed

**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #7**

2013-02-01 10:37

**MOT test number**

496622433085

**Result**

✓ Passed

**Notice** N/S/R and O/S/R brake discs corroded.**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)



**MOT #6** 2012-01-28 12:01**MOT test number** 856728422064**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Wipers poor**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2011-01-13 12:56**MOT test number** 716573611029**Result** ✓ Passed**MOT #4** 2009-10-28 12:41**MOT test number** 224081309355**Result** ✓ Passed**MOT #3** 2009-10-27 15:03**MOT test number** 892850109390**Result** ✗ Failed**Fail** Centre Rear Statutory seat belt missing (5.1.1)**MOT #2** 2009-04-09 16:50**MOT test number** 132899999009**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)





MOT #1	2008-04-23 12:56
MOT test number	941124218150
Result	✓ Passed
Advice	Offside Rear brake disc slightly pitted (3.5.1h)
Advice	Nearside Rear brake disc slightly pitted (3.5.1h)
Notice	O/s front tyre bold on inner edge , n/s front tyre wearing on inner edge .



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
26 July 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	26 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KX05WJL
Plate since	2020-06-29
Current registration	 KX05WJL
Plate since	2020-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-03-02
Last registration	2023-07-14
Complete history	<a href="#">See info</a>



Registration #1	2005-03-02	7 mi
Registration #2	2008-04-23	38.385 mi
Registration #3	2009-04-09	48.328 mi
Registration #4	2009-10-27	54.874 mi
Registration #5	2009-10-28	54.874 mi
Registration #6	2011-01-13	62.154 mi
Registration #7	2012-01-28	68.868 mi
Registration #8	2013-02-01	75.128 mi
Registration #9	2014-01-08	80.536 mi
Registration #10	2015-01-27	87.708 mi
Registration #11	2016-01-14	93.737 mi
Registration #12	2016-01-14	93.737 mi
Registration #13	2016-01-14	93.737 mi
Registration #14	2016-01-14	93.737 mi
Registration #15	2016-01-14	93.737 mi
Registration #16	2016-01-14	93.737 mi
Registration #17	2016-01-14	93.737 mi
Registration #18	2016-01-14	93.737 mi
Registration #19	2016-01-14	93.737 mi
Registration #20	2016-01-14	93.737 mi
Registration #21	2016-01-14	93.737 mi
Registration #22	2016-01-14	93.737 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1928 mm
Height	1723 mm
Length	4754 mm
Wheel base	2855 mm
Kerb weight	2510 kg
Max. allowed weight	2850 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5



Number of axles	2
Engine number	BAC 069514