



report date: 2024-03-29

General information

Make	BMW
Model	X3 D SE
Colour	Black
Year of manufacture	2006
Top speed	123 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	329 Nm at 2.000 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg
CO2 emission	191 g/km
CO2 label	J





## MOT history

MOT expiry date	2021-01-14
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	41
Total items failed	7

MOT #14 2020-01-15 13:57

MOT test number 991807645159

Result ✓ Passed

Next expiry date 2021-01-14

**Minor** Offside Rear Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #13 2020-01-14 17:52

MOT test number 349858555550

Result ✗ Failed

**Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**Minor** Offside Rear Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MAJOR** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #12** 2018-10-25 13:56**MOT test number** 632174221026**Result** ✓ Passed**Advice** Offside Front Suspension component pin or bush slightly worn bottom front arm (5.3.4 (a) (i))**Advice** Slight mist of oil leak around transmission system**Advice** Nearside Front Suspension component pin or bush slightly worn bottom front arm (5.3.4 (a) (i))**Advice** Nearside Front door dented**Advice** Covers fitted underneath the vehicle**MOT #11** 2018-10-25 11:18**MOT test number** 775072738804**Result** ✗ Failed**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front door dented**Advice** Offside Front Suspension component pin or bush slightly worn bottom front arm (5.3.4 (a) (i))**Advice** Covers fitted underneath the vehicle**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Suspension component pin or bush slightly worn bottom front arm (5.3.4 (a) (i))**Advice** Slight mist of oil leak around transmission system**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #10** 2017-10-27 07:59**MOT test number** 904498537953**Result** ✓ Passed

**MOT #9** 2017-09-23 13:50**MOT test number** 369666166119**Result** ✓ Passed

- Advice** Oil leak
- Advice** Offside Rear drive shaft boot insecure still protects joint
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear brake discs slight corroded
- Advice** Nearside Front tyre damage sidewall

**MOT #8** 2016-10-03 10:50**MOT test number** 565963245573**Result** ✓ Passed**MOT #7** 2016-10-03 10:50**MOT test number** 205412562425**Result** ✗ Failed

- Pass with rectification** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Pass with rectification** Nearside Rear Wheel bolt(s) missing (4.2.A.1e)
- Pass with rectification** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

**MOT #6** 2015-09-09 12:41**MOT test number** 242248703011**Result** ✓ Passed

- Advice** Under tray fitted obscuring components
- Advice** Nearside Rear Tyre worn close to the legal limit 2.0mm (4.1.E.1)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Engine cover fitted obscuring components
- Advice** Front discs worn and lipped
- Advice** Offside Rear Tyre worn close to the legal limit 2.0mm (4.1.E.1)

**MOT #5** 2014-09-29 13:18**MOT test number** 248582374247**Result** ✓ Passed

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Oil leak
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2014-09-29 11:05**MOT test number** 557372574234**Result** ✗ Failed

- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Oil leak
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Rear coil spring broken (2.4.C.1a)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #3** 2013-10-07 15:11**MOT test number** 156980683237**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2013-10-04 12:50**MOT test number** 889147073232**Result** ✗ Failed**Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2012-10-08 16:44**MOT test number** 875282782285**Result** ✓ Passed**Notice** Offside front tyre worn on outer edge**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕  
Untaxed

Tax expired:  
1 November 2020

✕  
MOT

Expired:  
14 January 2021

Tax status	Expired at 1 November 2020
Days left	1275 days too late
MOT expiry date	14 January 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2019-06-29
Current registration	
Plate since	2019-06-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2006-06-28
Last registration	2020-01-15
Complete history	<a href="#">See info</a>



Registration #1	2006-06-28	24 mi
Registration #2	2012-10-08	60.594 mi
Registration #3	2013-10-04	78.886 mi
Registration #4	2013-10-07	79.010 mi
Registration #5	2014-09-29	97.869 mi
Registration #6	2014-09-29	97.869 mi
Registration #7	2015-09-09	110.860 mi
Registration #8	2016-10-03	124.679 mi
Registration #9	2016-10-03	124.679 mi
Registration #10	2016-10-03	124.679 mi
Registration #11	2016-10-03	124.679 mi
Registration #12	2016-10-03	124.679 mi
Registration #13	2016-10-03	124.679 mi
Registration #14	2016-10-03	124.679 mi
Registration #15	2016-10-03	124.679 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1853 mm
Height	1674 mm
Length	4565 mm
Wheel base	2795 mm
Kerb weight	1540 kg
Max. allowed weight	2265 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	80896212