



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO ZETEC 136PS
Colour	Grey
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	319 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-09
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-09
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	32
Total items failed	22

MOT #20	2023-07-25 14:46
MOT test number	289263009869
Result	✓ Passed
Next expiry date	2024-08-09
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Seat belt slightly damaged (7.1.2 (b) (i))

MOT #19	2023-07-25 10:18
MOT test number	918804469155
Result	✗ Failed
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Seat belt slightly damaged (7.1.2 (b) (i))
Fail	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #18**

2022-07-19 09:43

MOT test number

805402985117

Result

✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #17**

2021-08-10 10:20

MOT test number

164338677386

Result

✓ Passed

MOT #16

2020-07-07 15:21

MOT test number

855666789516

Result

✓ Passed

MOT #15

2020-07-03 11:30

MOT test number

858051250820

Result

✗ Failed

Fail Nearside Rear Suspension component pin or bush excessively worn Trailing arm Front bush (5.3.4 (a) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Rear Brake slack adjuster seized (1.1.18 (a))**Fail** Offside Rear Suspension component pin or bush excessively worn Trailing arm Front bush (5.3.4 (a) (i))**Fail** Offside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))



MOT #14	2019-07-01 14:25
MOT test number	837519746217
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2019-07-01 10:04
MOT test number	194045881055
Result	✗ Failed
Fail	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #12	2018-06-13 14:06
MOT test number	380489893284
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2018-06-13 09:15

MOT test number

505167331874

Result**✗ Failed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Position lamp not working front & rear (4.2.1 (a))**MOT #10**

2017-06-01 09:18

MOT test number

527150048855

Result**✓ Passed****Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**MOT #9**

2017-06-01 09:18

MOT test number

881373599988

Result**✗ Failed****Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

**MOT #8** 2016-06-20 09:03**MOT test number** 160777256344**Result** ✓ Passed

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #7 2016-06-16 11:41**MOT test number** 555287024664**Result** ✗ Failed

Fail Offside Track rod end ball joint has excessive play (2.2.B.1f)

Pass with rectification Nearside Headlamp not working on dipped beam (1.7.5a)

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #6 2015-06-18 09:52**MOT test number** 797409865119**Result** ✓ Passed**MOT #5** 2014-06-03 16:09**MOT test number** 496944654124**Result** ✓ Passed**MOT #4** 2014-06-03 10:04**MOT test number** 456884254103**Result** ✗ Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #3** 2013-06-13 11:03**MOT test number** 637974963181**Result** ✓ Passed**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)**MOT #2** 2013-06-13 11:03**MOT test number** 495264763161**Result** ✗ Failed**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #1** 2013-04-10 12:57**MOT test number** 179250103187**Result** ✓ Passed**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Front brake discs slightly scored**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
9 August 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	9 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	SL10YZC
Plate since	2019-03-28
Current registration	SL10YZC
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-05-28
Last registration	2023-07-25
Complete history	See info



Registration #1	2010-05-28	28 mi
Registration #2	2013-04-10	26.810 mi
Registration #3	2013-06-13	28.666 mi
Registration #4	2014-06-03	43.572 mi
Registration #5	2014-06-03	43.572 mi
Registration #6	2015-06-18	63.673 mi
Registration #7	2016-06-16	82.908 mi
Registration #8	2016-06-20	83.124 mi
Registration #9	2017-06-01	98.275 mi
Registration #10	2017-06-01	98.275 mi
Registration #11	2018-06-13	108.798 mi
Registration #12	2019-06-20	121.277 mi
Registration #13	2020-06-20	133.757 mi
Registration #14	2021-06-20	146.237 mi
Registration #15	2022-06-20	158.717 mi
Registration #16	2023-06-20	171.197 mi
Registration #17	2024-06-20	183.677 mi
Registration #18	2025-06-20	196.157 mi
Registration #19	2026-06-20	208.637 mi
Registration #20	2027-06-20	221.117 mi
Registration #21	2028-06-20	233.597 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

AB89987