



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D3 DRIVE ES
Colour	Black
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	149 g/km
CO2 label	F






Internet history

Entry 1

Date	2022-01-20
Pictures	32
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-30
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	22
Total items failed	2

MOT #12	2023-09-28 11:07
MOT test number	411752490010
Result	✓ Passed
Next expiry date	2024-09-30
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11	2022-10-01 08:17
MOT test number	268115351381
Result	✓ Passed
Minor	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Brake disc worn, pitted or scored, but not seriously weakened both front brake discs corroding (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing perishing/advice replacement (5.2.3 (d) (ii))
Advice	Tyre slightly damaged/cracking or perishing both front tyres perishing/advice replacement (5.2.3 (d) (ii))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #10	2021-10-01 16:10
MOT test number	581743694616
Result	✓ Passed

**MOT #9** 2021-03-01 11:17**MOT test number** 370376919575**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #8** 2021-02-19 10:41**MOT test number** 222828626796**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #7** 2020-02-21 09:59**MOT test number** 776755233144**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #6** 2019-02-22 09:48**MOT test number** 931057069129**Result** ✓ Passed

**MOT #5** 2018-02-23 09:46**MOT test number** 245928101796**Result** ✓ Passed**MOT #4** 2018-02-23 09:46**MOT test number** 983439552439**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2017-02-17 09:56**MOT test number** 946127896635**Result** ✓ Passed**Advice** Front and rear discs lipped**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #2** 2016-02-16 15:32**MOT test number** 731709683796**Result** ✓ Passed**Advice** Front and rear discs lipped**MOT #1** 2015-02-23 09:54**MOT test number** 176214355491**Result** ✓ Passed**Notice** Nail in nearside rear tyre**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
30 September 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	30 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-03-30
Last registration	2023-09-28
Complete history	See info



Registration #1	2012-03-30	8 mi
Registration #2	2015-02-23	44.605 mi
Registration #3	2016-02-16	51.374 mi
Registration #4	2017-02-17	57.523 mi
Registration #5	2018-02-23	62.434 mi
Registration #6	2018-02-23	62.434 mi
Registration #7	2019-02-22	64.881 mi
Registration #8	2019-02-22	64.881 mi
Registration #9	2019-02-22	64.881 mi
Registration #10	2019-02-22	64.881 mi
Registration #11	2019-02-22	64.881 mi
Registration #12	2019-02-22	64.881 mi
Registration #13	2019-02-22	64.881 mi
Registration #14	2019-02-22	64.881 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1756 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1161516