



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 S S40
Colour	Grey
Year of manufacture	2010
Top speed	115 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-08-27
Pictures	7
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-06-22
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	50
Total items failed	10

MOT #17 2023-06-20 08:43

MOT test number 941132549774

Result ✓ Passed

Next expiry date 2024-06-22

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement  
Wishbone - rear bush worn (5.3.4 (a) (i))

**Advice** Nearside Rear Nail in tyre

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement  
Wishbone - rear bush worn (5.3.4 (a) (i))

MOT #16 2022-05-25 09:29

MOT test number 943509354886

Result ✓ Passed

**Advice** Vehicles internal headlight adjuster altered to recheck lights

**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Wishbone,  
rear bushes worn. Both sides. (5.3.4 (a) (i))

MOT #15 2021-06-23 07:40

MOT test number 247940480402

Result ✓ Passed

**Advice** Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)  
(i))

**MOT #14** 2021-06-22 12:01**MOT test number** 431946817708**Result** ✗ Failed**Advice** Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #13** 2021-02-01 12:12**MOT test number** 743917753668**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin Pads @ 3mm (1.1.13 (a) (ii))**MOT #12** 2021-01-26 12:36**MOT test number** 107100385102**Result** ✗ Failed**Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Rear Brake pad(s) wearing thin Pads @ 3mm (1.1.13 (a) (ii))**MOT #11** 2020-01-23 11:56**MOT test number** 577411127614**Result** ✓ Passed

**MOT #10**

2019-12-30 16:17

**MOT test number**

934516353346

**Result**

✓ Passed

**Advice**

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9**

2018-08-07 07:35

**MOT test number**

501013645995

**Result**

✓ Passed

**MOT #8**

2018-05-11 10:53

**MOT test number**

618247487779

**Result**

✓ Passed

**Advice**

Nearside Front Macpherson strut corroded but not seriously weakened (2.4.G.1)

**Advice**

Front Sub-frame corroded but not seriously weakened (2.4.G.1)

**Advice**

Vehicle fitted with side skirts and engine under tray obscuring the view of some components

**Advice**

Nearside Rear Lower Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice**

Offside Front Lower Suspension arm corroded but not seriously weakened (2.4.G.1)

**Advice**

Offside Rear Suspension arm corroded but not seriously weakened (2.4.G.1)

**Advice**

Offside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Outer bush (2.4.G.2)

**Advice**

Offside Front Macpherson strut corroded but not seriously weakened (2.4.G.1)

**Advice**

Nearside Front Lower Suspension arm corroded but not seriously weakened (2.4.G.1)

**Advice**

Offside Rear Lower Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice**

Nearside Rear Suspension arm corroded but not seriously weakened (2.4.G.1)

**Advice**

Nearside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Outer bush (2.4.G.2)

**MOT #7**

2018-05-11 07:41

**MOT test number**

462905922153

**Result****✗ Failed**

- Advice** Offside Rear Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice** Offside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Outer bush (2.4.G.2)
- Advice** Offside Front Macpherson strut corroded but not seriously weakened (2.4.G.1)
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice** Offside Rear Lower Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (2.4.G.1)
- Fail** Offside Rear Tyre has ply or cords exposed Tyre is cracked in the tread exposing cord or ply 205/50/17 (4.1.D.1b)
- Advice** Vehicle fitted with side skirts and engine under tray obscuring the view of some components
- Advice** Nearside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Outer bush (2.4.G.2)
- Advice** Nearside Front Macpherson strut corroded but not seriously weakened (2.4.G.1)
- Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice** Nearside Rear Lower Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (2.4.G.1)
- Fail** Nearside Rear Tyre has ply or cords exposed Cracked in the tread exposing cord or ply 205/50/17 (4.1.D.1b)

**MOT #6**

2017-04-27 07:46

**MOT test number**

926035964299

**Result****✓ Passed****MOT #5**

2016-05-10 08:32

**MOT test number**

380671834183

**Result****✓ Passed**

**MOT #4** 2015-05-13 12:26**MOT test number** 757413435117**Result** ✓ Passed

- Advice** Offside Front Upper Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** OFFSIDE FRONT HEADLAMP AIM IS AT ITS LOWEST ACCEPTABLE LEVEL..WILL REQUIRE AJUSTEMENT
- Notice** ALL FOUR COIL SPRINGS ARE SLIGHTLY CORRODED
- Advice** Nearside Front Upper Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** FUEL LIGHT ON..ON THE DASH
- Notice** ALL FOUR BRAKE DISCS ARE WORN

**MOT #3** 2014-05-17 10:25**MOT test number** 525627534119**Result** ✓ Passed

- Notice** Plastic trim on sills
- Notice** All four brake discs slightly worn
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #2** 2014-05-17 10:25**MOT test number** 515477734182**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** All four brake discs slightly worn
- Pass with rectification** Offside Front Headlamp aim too low (1.8)
- Notice** Plastic trim on sills



MOT #1	2013-05-03 09:54
MOT test number	438563723151
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 April 2025

✓  
**MOT**  
  
Expires:  
22 June 2024

Tax status	Valid until 1 April
Days left	338
MOT expiry date	22 June 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-05-06
Last registration	2023-06-20
Complete history	<a href="#">See info</a>



Registration #1	2010-05-06	27 mi
Registration #2	2013-05-03	7.579 mi
Registration #3	2014-05-17	13.422 mi
Registration #4	2015-05-13	16.198 mi
Registration #5	2016-05-10	19.564 mi
Registration #6	2017-04-27	21.529 mi
Registration #7	2018-05-11	22.962 mi
Registration #8	2018-05-11	22.962 mi
Registration #9	2018-08-07	23.697 mi
Registration #10	2019-05-20	25.377 mi
Registration #11	2019-05-20	25.377 mi
Registration #12	2019-05-20	25.377 mi
Registration #13	2019-05-20	25.377 mi
Registration #14	2019-05-20	25.377 mi
Registration #15	2019-05-20	25.377 mi
Registration #16	2019-05-20	25.377 mi
Registration #17	2019-05-20	25.377 mi
Registration #18	2019-05-20	25.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1322 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	203397