



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI KOMBI
Colour	Silver
Year of manufacture	2014
Top speed	116 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	75 kW / 102 HP / 138 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 2

Date	2021-08-29
Pictures	0
Listing price	View report

source: heycar.co.uk

Entry 1

Date	2021-08-28
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-03-03
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	7
Total items failed	0

MOT #9	2024-02-15 16:26
MOT test number	665126761242
Result	✓ Passed
Next expiry date	2025-03-03

MOT #8	2023-02-27 09:58
MOT test number	129933046436
Result	✓ Passed
Advice	Nearside Front Shock absorbers has light misting of oil suspension strut (5.3.2 (b))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7	2022-02-24 16:09
MOT test number	426412329799
Result	✓ Passed
Advice	Nearside Front Shock absorbers has light misting of oil suspension strut (5.3.2 (b))

MOT #6	2022-02-22 14:23
MOT test number	397508898074
Result	✗ Failed
Advice	Nearside Front Shock absorbers has light misting of oil suspension strut (5.3.2 (b))
MAJOR	Nearside Rear Leaf spring fractured (5.3.1 (b) (i))

**MOT #5** 2021-02-24 12:40**MOT test number** 393352522190**Result** ✓ Passed**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #4** 2020-03-04 14:59**MOT test number** 277115775022**Result** ✓ Passed**MOT #3** 2019-02-05 12:05**MOT test number** 855819151085**Result** ✓ Passed**MOT #2** 2018-02-14 10:17**MOT test number** 136594759102**Result** ✓ Passed**MOT #1** 2017-02-23 09:05**MOT test number** 326442140008**Result** ✓ Passed



Tax & MOT check

×

Untaxed

Tax expired:
30 October 2023

✓

MOT

Expires:
3 March 2025

Tax status	Expired at 30 October 2023
Days left	182 days too late
MOT expiry date	3 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SY14LHA
Plate since	2019-03-29
Current registration	 SY14LHA
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-01
Last registration	2024-02-15
Complete history	See info



Registration #1	2014-03-01	29 mi
Registration #2	2017-02-23	56.863 mi
Registration #3	2018-02-14	62.723 mi
Registration #4	2019-02-05	68.554 mi
Registration #5	2020-03-04	73.500 mi
Registration #6	2021-02-24	76.603 mi
Registration #7	2022-03-01	79.557 mi
Registration #8	2023-03-01	82.511 mi
Registration #9	2024-03-01	85.465 mi
Registration #10	2025-03-01	88.419 mi
Registration #11	2026-03-01	91.373 mi
Registration #12	2027-03-01	94.327 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	179 mm
Length	488 mm
Wheel base	301 mm
Kerb weight	1659 kg
Max. allowed weight	2280 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

CAYDZ80458