

Ford



General information

| Make | FORD |
|---------------------|----------------|
| Model | FOCUS ST-3 |
| Colour | Grey |
| Year of manufacture | 2010 |
| Top speed | 150 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 223 BHP | 0 < 101 A |
|-------------------------|---------------------|-----------|
| Max. torque | 320 Nm at 4.000 rpm | 101 - 120 |
| Engine capacity | 2.521 сс | 121 - 140 |
| Cylinders | 5 | 141 - 165 |
| Fuel type | Petrol | 166 - 185 |
| Consumption city | 20.5 mpg | 186 - 225 |
| Consumption extra urban | 41.5 mpg | 225+ |
| Consumption combined | 30.4 mpg | |
| CO2 emission | 224 g/km | |
| CO2 label | К | |
| | | |



| 2021-01-30 |
|-------------|
| 1 |
| View report |
| |



source: autoonline.co.uk



MOT history

| MOT expiry date | 2025-01-03 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 11 |
| Failed MOT tests | 0 |
| Total advice items | 20 |
| Total items failed | 0 |

| MOT #11 | 2024-01-03 14:55 |
|---|------------------|
| MOT test number | 199420290853 |
| Result | Passed |
| Next expiry date | 2025-01-03 |
| Advice Oil leak, but not excessive gearbox (8.4.1 (a) (i)) | |
| Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated slight grease | |

| MOT #10 | 2022-12-21 11:36 |
|-----------------|------------------|
| MOT test number | 415266525842 |
| Result | Passed |
| | |
| МОТ #9 | 2021-12-22 12:51 |
| MOT test number | 530957112429 |

Result

seepage (6.1.7 (g) (i))

| MOT #8 | | 2021-01-04 12:50 |
|------------------------|--|-----------------------|
| MOT test | number | 626536030612 |
| Result | | ✓ Passed |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice (d) (i)) | Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or c | ords side wall (5.2.3 |

🗸 Passed





| MOT #7 | | 2019-05-29 10:41 |
|--|--|------------------|
| MOT test | number | 157220011007 |
| Result | | ✓ Passed |
| Advice | Nearside rear tyre has damage to outer sidewall | |
| MOT #6 | | 2018-05-12 10:21 |
| MOT test | number | 941260396268 |
| Result | | ✓ Passed |
| Advice | Nearside rear tyre has damage to outer sidewall | |
| | | |
| MOT #F | | 2017 05 17 14.40 |
| MOT #5 | num b n n | 2017-05-17 14:48 |
| MOT test | number | 917994794616 |
| | number | |
| MOT test | number Offside Front Tyre worn close to the legal limit at minimum (4.1.E.1) | 917994794616 |
| MOT test Result | | 917994794616 |
| MOT test Result Advice | Offside Front Tyre worn close to the legal limit at minimum (4.1.E.1) | 917994794616 |
| MOT test Result Advice Advice | Offside Front Tyre worn close to the legal limit at minimum (4.1.E.1) Offside Rear Tyre worn close to the legal limit (4.1.E.1) | 917994794616 |



| | CAR CHECK | EF10BYX report date: 2024-03-28 |
|----------|--|------------------------------------|
| MOT #4 | | 2016-05-21 11:30 |
| MOT test | number | 648960862838 |
| Result | | ✓ Passed |
| Advice | Front brake discs are slightly worn and lipped | |
| Advice | Offside rear tyre is out of shape slightly on inner shoulder | |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |

| Advice Er | ingine covers and under trays fitted obscuring some components |
|------------------|--|
| Advice Ne | learside rear tyre is worn and out of shape on the inner edge |
| Advice Ne | learside Front Tyre worn close to the legal limit (4.1.E.1) |

| MOT #3 | 2015-06-08 14:08 |
|-------------------------------|------------------|
| MOT test number | 925959655142 |
| Result | ✓ Passed |
| Notice Front wiper blade worn | |

| MOT #2 | 2014-05-17 10:27 |
|-----------------|------------------|
| MOT test number | 237967934473 |
| Result | ✓ Passed |

| MOT #1 | | 2013-05-02 15:14 |
|----------|---|------------------|
| MOT test | number | 128232223193 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |



Tax & MOT check

| √ Taxed | √ мот |
|-------------------------|----------------------------|
| Tax due: 1 June 2024 | Expires: 3 January 2025 |
| Tax status | Valid until 1 June |
| Days left | 34 |
| MOT expiry date | 3 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | К |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|--|-------|
| Date | F | |
| Category | | ARME |
| Туре | | |
| Damage 2 | | AMPLE |
| | E E | |
| Date | | \$ |
| Category | AMP | |
| Туре | No. Contraction of the second se | |

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 |





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| *********** | |
| ******* | |
| ****** | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 13 |
| First mileage registration | 2010-05-28 |
| Last registration | 2024-01-03 |
| Complete history | <u>See info</u> |



| Registration #1 | 2010-05-28 | 24 mi |
|------------------|------------|------------|
| Registration #2 | 2013-05-02 | 18.559 mi |
| Registration #3 | 2014-05-17 | 22.663 mi |
| Registration #4 | 2015-06-08 | 26.424 mi |
| Registration #5 | 2016-05-21 | 28.117 mi |
| Registration #6 | 2017-05-17 | 30.782 mi |
| Registration #7 | 2018-05-12 | 38.764 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.117 mi |





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

**** see crash video



| Dimensions & weight | |
|------------------------|-----------------------|
| Width | 1839 mm |
| Height | 1497 mm |
| Length | 4357 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1437 kg |
| Max. allowed weight | 1890 kg |
| Additional information | |
| Fuel tank capacity | 55 I |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 4 |

Number of seats CarCheck.co.uk

| Number of axles | 2 |
|-----------------|---------|
| Engine number | AU03984 |