



RENAULT




report date: 2024-03-29

## General information

<b>Make</b>	RENAULT
<b>Model</b>	TRAFIC LL29 STANDARD DCI 115
<b>Colour</b>	Silver
<b>Year of manufacture</b>	2013
<b>Top speed</b>	93 mph
<b>Gearbox</b>	6 speed Manual

## Engine & fuel consumption

<b>Power</b>	115 BHP
<b>Max. torque</b>	300 Nm at 1.500 rpm
<b>Engine capacity</b>	1.995 cc
<b>Cylinders</b>	4
<b>Fuel type</b>	Diesel
<b>Consumption city</b>	32.8 mpg
<b>Consumption extra urban</b>	47.9 mpg
<b>Consumption combined</b>	40.9 mpg
<b>CO2 emission</b>	190 g/km
<b>CO2 label</b>	J





## Internet history

### Entry 2


Date	2021-10-18
Pictures	13
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 1

Date	2021-09-16
Pictures	14
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

<b>MOT expiry date</b>	2023-05-05
<b>MOT pass rate</b>	60 %
<b>MOT passed</b>	9
<b>Failed MOT tests</b>	6
<b>Total advice items</b>	40
<b>Total items failed</b>	26

**MOT #15** 2022-05-06 15:44

**MOT test number** 946545506626

**Result** ✓ Passed

**Next expiry date** 2023-05-05

- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Play in steering rack inner joint(s)
- Advice** Centre stop light not working



MOT #14 2022-05-06 15:44

MOT test number 332404587758

Result ✗ Failed

**Pass with rectification** Offside Front Headlamp light intensity severely reduced (4.1.4 (a))

**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**Advice** Play in steering rack inner joint(s)

**Advice** Centre stop light not working

**Pass with rectification** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #13 2021-06-08 13:26

MOT test number 140385794566

Result ✓ Passed

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Brake pedal wearing smooth (1.1.2 (c))



MOT #12 2021-06-07 14:11

MOT test number 769152403115

Result ✗ Failed

**Fail** Offside Rear Passenger's seat backrest cannot be secured in the upright position. CENTRE ROW (6.2.6 (a) (i))

**Advice** Nearside Rear Outer Seat belt webbing slightly damaged or frayed CENTRE FOW (7.1.2 (b) (ii))

**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Brake pedal wearing smooth (1.1.2 (c))

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Offside Rear Outer Seat belt webbing slightly damaged or frayed CENTRE ROW (7.1.2 (b) (ii))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #11 2021-02-26 09:03

MOT test number 363469081776

Result ✓ Passed

**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Nearside Outer Seat belt webbing slightly damaged or frayed centre row (7.1.2 (b) (ii))

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

**Advice** Brake pedal wearing smooth (1.1.2 (c))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

**Advice** Offside Outer Seat belt webbing slightly damaged or frayed centre row (7.1.2 (b) (ii))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))



MOT #10

2021-02-18 13:08

MOT test number

693602666006

Result

✗ Failed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Fail** Offside Headlamp aim not tested (4.1.2 (b))
- Fail** Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Front Windscreen wiper does not clear the windscreen effectively both sides (3.4 (b) (ii))
- Fail** Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))
- Fail** Nearside Outer Passenger's seat backrest cannot be secured in the upright position. centre row (6.2.6 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Outer Seat belt webbing slightly damaged or frayed centre row (7.1.2 (b) (ii))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Front Sub-frame pin or bush excessively worn both sides rear bushes (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Fail** Nearside Reversing lamp inoperative (4.6.1 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Fail** Offside Brake pipe excessively corroded front to rear (1.1.11 (c))
- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))
- Advice** Nearside Outer Seat belt webbing slightly damaged or frayed centre row (7.1.2 (b) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))



MOT #9 2019-08-27 12:00

MOT test number 130208203766

Result ✓ Passed

MOT #8 2019-08-23 13:18

MOT test number 463334704071

Result ✗ Failed

**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**Fail** Offside Headlamp levelling device inoperative (4.1.5 (a))

MOT #7 2018-12-28 09:32

MOT test number 398577423275

Result ✓ Passed

MOT #6 2018-10-11 08:47

MOT test number 876595584968

Result ✗ Failed

**Fail** Offside Headlamp aim too low (4.1.2 (a))

**Fail** Exhaust shield missing where fitted as original equipment creating a risk of fire heat shield missing at fuel tank area (6.1.3 (e))

**Fail** Offside Headlamp levelling device inoperative (4.1.5 (a))

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened on inner edge (1.1.14 (a) (ii))

**Fail** Nearside Headlamp aim too low (4.1.2 (a))

**Fail** Nearside Headlamp levelling device inoperative (4.1.5 (a))

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened on inner edge (1.1.14 (a) (ii))

MOT #5 2017-08-04 08:25

MOT test number 512999798544

Result ✓ Passed



**MOT #4** 2016-08-08 12:57

**MOT test number** 583244241980

**Result** ✓ Passed

**MOT #3** 2016-08-04 08:45

**MOT test number** 401526448244

**Result** ✗ Failed

**Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

**Fail** Front Headlamp switch faulty Not locking on Main Beam Position (1.7.1)

**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #2** 2015-08-04 09:24

**MOT test number** 526106815237

**Result** ✓ Passed

**MOT #1** 2014-08-04 09:33

**MOT test number** 819146814226

**Result** ✓ Passed



Tax & MOT check

**X**  
**Untaxed**

**Tax expired:**  
1 November 2023

**X**  
**MOT**

**Expired:**  
5 May 2023

<b>Tax status</b>	Expired at 1 November 2023
<b>Days left</b>	181 days too late
<b>MOT expiry date</b>	5 May 2023
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-




**Damage history**

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.


**Damage 1**

<b>Date</b>	
<b>Category</b>	
<b>Type</b>	



**Damage 2**

<b>Date</b>	
<b>Category</b>	
<b>Type</b>	



**Extra RENAULT salvage check**



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

**More info >**



**Vehicle valuation**

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	SE13DZN
Plate since	2019-09-29
Current registration	SE13DZN
Plate since	2019-09-29

More info >



**Finance check**

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	18
<b>First mileage registration</b>	2013-08-19
<b>Last registration</b>	2022-05-06
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2013-08-19	10 mi
<b>Registration #2</b>	2014-08-04	36.549 mi
<b>Registration #3</b>	2015-08-04	95.731 mi
<b>Registration #4</b>	2016-08-04	134.418 mi
<b>Registration #5</b>	2016-08-08	134.537 mi
<b>Registration #6</b>	2017-08-04	154.914 mi
<b>Registration #7</b>	2018-10-11	174.470 mi
<b>Registration #8</b>	2018-12-28	174.499 mi
<b>Registration #9</b>	2019-08-23	195.563 mi
<b>Registration #10</b>	2019-08-23	195.563 mi
<b>Registration #11</b>	2019-08-23	195.563 mi
<b>Registration #12</b>	2019-08-23	195.563 mi
<b>Registration #13</b>	2019-08-23	195.563 mi
<b>Registration #14</b>	2019-08-23	195.563 mi
<b>Registration #15</b>	2019-08-23	195.563 mi
<b>Registration #16</b>	2019-08-23	195.563 mi
<b>Registration #17</b>	2019-08-23	195.563 mi
<b>Registration #18</b>	2019-08-23	195.563 mi

[More info >](#)



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★☆☆
Adult	58%
Children	79%
Pedestrian	28%
Safety systems	14%
Overall rating	51%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1904 mm
Height	1954 mm
Length	5182 mm
Kerb weight	1907 kg
Max. allowed weight	3055 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	9
Number of axles	2

