



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	IQ VVT-I IQ
Colour	Blue
Year of manufacture	2010
Top speed	93 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	91 Nm at 4.800 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	57.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-07-08
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



## MOT history

MOT expiry date	2025-03-15
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	24
Total items failed	6

MOT #14	2024-03-11 13:10
MOT test number	478614233585
Result	✓ Passed
Next expiry date	2025-03-15
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #13	2023-03-16 14:10
MOT test number	810676279187
Result	✓ Passed

MOT #12	2022-03-15 18:09
MOT test number	490062166631
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #11	2021-08-26 15:39
MOT test number	908914242867
Result	✓ Passed
Minor	Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #10** 2020-08-17 13:55**MOT test number** 860173115897**Result** ✓ Passed**MOT #9** 2020-08-11 11:44**MOT test number** 690777244848**Result** ✗ Failed

- Fail** Offside Rear Brake pipe excessively corroded of main (1.1.11 (c))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Rear Emissions not tested (8.2.1.2 (d))

**MOT #8** 2019-03-22 14:46**MOT test number** 751347243668**Result** ✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #7** 2018-04-13 08:34**MOT test number** 504085492630**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin both fronts (3.5.1g)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both rears (3.5.1i)
- Advice** Rear Brake pad(s) wearing thin both rears (3.5.1g)

**MOT #6**

2017-04-14 10:15

**MOT test number**

431197337518

**Result**

✓ Passed

- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Engine covers / under trays fitted obscuring view to some components
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #5**

2017-04-14 10:15

**MOT test number**

208928190078

**Result**

✗ Failed

- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Engine covers / under trays fitted obscuring view to some components
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4**

2016-04-18 08:42

**MOT test number**

917285408488

**Result**

✓ Passed

- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #3** 2015-04-02 15:47**MOT test number** 237222995078**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2014-04-14 09:41**MOT test number** 557444604162**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-04-12 10:25**MOT test number** 165122403145**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
15 March 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	305
<b>MOT expiry date</b>	15 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-05-21
Last registration	2024-03-11
Complete history	<a href="#">See info</a>



Registration #1	2010-05-21	10 mi
Registration #2	2013-04-12	23.043 mi
Registration #3	2014-04-14	28.311 mi
Registration #4	2015-04-02	34.066 mi
Registration #5	2016-04-18	37.486 mi
Registration #6	2017-04-14	39.916 mi
Registration #7	2017-04-14	39.916 mi
Registration #8	2018-04-13	41.929 mi
Registration #9	2019-05-20	45.277 mi
Registration #10	2020-05-20	48.277 mi
Registration #11	2021-05-20	51.277 mi
Registration #12	2022-05-20	54.277 mi
Registration #13	2023-05-20	57.277 mi
Registration #14	2024-03-11	60.277 mi
Registration #15	2024-03-11	60.277 mi
Registration #16	2024-03-11	60.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	845 kg
Max. allowed weight	1215 kg

Additional information

Fuel tank capacity	32 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Engine number	1KR0998678
---------------	------------