



report date: 2024-03-29

General information

Make	SUZUKI
Model	SX4 SZ5
Colour	Silver
Year of manufacture	2014
Top speed	109 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	145 Nm at 4.400 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	149 g/km
CO2 label	F



Internet history

Entry 1

Date	2021-06-15
Pictures	7
Listing price	<a href="#">View report</a>



source: yesauto.com



## MOT history

MOT expiry date	2024-08-30
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	29
Total items failed	4

## MOT #10 2023-08-31 14:59

MOT test number 660625875643

Result ✓ Passed

Next expiry date 2024-08-30

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

## MOT #9 2023-08-27 13:05

MOT test number 881052776396

Result ✗ Failed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords and low tread (5.2.3 (d) (i))



MOT #8 2022-08-08 14:45

MOT test number 509631799283

Result ✓ Passed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Nail in tyre
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #7 2022-08-08 14:26

MOT test number 762084171152

Result ✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Headlamp aim too high and too far to the left. (4.1.2 (a))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Nail in tyre
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #6** 2021-07-30 17:50**MOT test number** 921523669832**Result** ✓ Passed**MOT #5** 2021-07-16 13:24**MOT test number** 834765507418**Result** ✓ Passed**MOT #4** 2020-08-08 14:49**MOT test number** 828835116806**Result** ✓ Passed**MOT #3** 2019-08-05 16:59**MOT test number** 369555346394**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge both rear tyres (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))**MOT #2** 2018-08-04 09:48**MOT test number** 854328153562**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #1	2017-07-11 13:41
MOT test number	501775646979
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
30 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	30 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-07-25
Last registration	2023-08-31
Complete history	<a href="#">See info</a>



Registration #1	2014-07-25	8 mi
Registration #2	2017-07-11	21.179 mi
Registration #3	2018-08-04	30.056 mi
Registration #4	2019-08-05	33.068 mi
Registration #5	2020-08-08	35.388 mi
Registration #6	2020-08-08	35.388 mi
Registration #7	2020-08-08	35.388 mi
Registration #8	2020-08-08	35.388 mi
Registration #9	2020-08-08	35.388 mi
Registration #10	2020-08-08	35.388 mi
Registration #11	2020-08-08	35.388 mi
Registration #12	2020-08-08	35.388 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	80%
Pedestrian	72%
Safety systems	81%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1730 mm
Height	1570 mm
Length	4120 mm
Wheel base	2500 mm
Kerb weight	1200 kg
Max. allowed weight	1685 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-1851492