



General information

Make	FIAT
Model	DOBLO JTD ACTIVE (120BHP)
Colour	Black
Year of manufacture	2009
Top speed	108 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	210 Nm at 3.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	45.6 mpg
CO2 emission	163 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-07-12
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-22
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	33
Total items failed	19

MOT #19	2023-07-18 08:37
MOT test number	615630488652
Result	✓ Passed
Next expiry date	2024-07-22
Advice	Parking brake lever defective but can be satisfactorily operated long travel (1.1.6 (d))
Advice	Steering rack boots covered in oil
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))
Advice	Offside Rear Service brake fluctuating, but not excessively 30kgf (1.2.1 (e))
Advice	Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn edges // 3mm (5.2.3 (e))
Advice	Nearside Rear Service brake fluctuating, but not excessively 50kgf (1.2.1 (e))

**MOT #18**

2023-07-12 09:44

MOT test number

396116994273

Result

✗ Failed

Advice Nearside Rear Service brake fluctuating, but not excessively 50kgf (1.2.1 (e))**Fail** Offside Front Lower Suspension arm ball joint excessively worn under load using shake plates (5.3.4 (a) (i))**Advice** Parking brake lever defective but can be satisfactorily operated long travel (1.1.6 (d))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn edges // 3mm (5.2.3 (e))**Fail** Offside Outer Seat belt anchorage prescribed area strength or continuity significantly reduced door sill (7.1.1 (a) (i))**Fail** Nearside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength door sill (5.3.6 (a) (i))**Advice** Steering rack boots covered in oil**Fail** Emissions unable to be completed due to exhaust blow (8.2.2.2 (e))**Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Service brake fluctuating, but not excessively 30kgf (1.2.1 (e))**Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))**Fail** Offside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill by rear leaf spring mount (5.3.6 (a) (ii))**Fail** Rear Exhaust has a major leak of exhaust gases silencer split open (6.1.2 (a))**MOT #17**

2022-07-22 08:12

MOT test number

952783950655

Result

✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Both outer sills are corroding**Advice** Offside Front tyre is worn on edges

**MOT #16**

2022-07-20 08:15

MOT test number

818451213092

Result**✗ Failed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Both outer sills are corroding**Fail** Offside Front Direction indicator not working (4.4.1 (a) (ii))**Pass with rectification** Offside Headlamp aim too high done (4.1.2 (a))**Fail** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**Advice** Offside Front tyre is worn on edges**Pass with rectification** Nearside Headlamp aim too high done (4.1.2 (a))**MOT #15**

2021-07-23 12:50

MOT test number

899708698589

Result**✓ Passed****MOT #14**

2020-10-30 11:56

MOT test number

948596998786

Result**✓ Passed****Advice** Slight lift in n/s/f strutt top bearing**MOT #13**

2019-10-14 14:01

MOT test number

594177313413

Result**✓ Passed****Advice** Exhaust mounting defective Both Front & Rear Exhaust Rubbers Perished/Cracked (6.1.2 (a))**Advice** Nearside Non obligatory mirror damaged**Advice** Offside Rear Brake cable damaged but not to excess (1.1.15 (a))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12** 2018-10-24 06:49**MOT test number** 124444486618**Result** ✓ Passed**MOT #11** 2018-10-18 07:29**MOT test number** 357958918337**Result** ✗ Failed

- Fail** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))
- Fail** Offside Headlamp aim too low (4.1.2 (a))
- Fail** Exhaust diesel particulate filter shows evidence of tampering. (8.2.2.1 (c))

MOT #10 2017-10-19 07:58**MOT test number** 572143229456**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit Inner edge. (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit Inner edge. (4.1.E.1)

MOT #9 2017-10-18 11:06**MOT test number** 265317631680**Result** ✗ Failed

- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Offside Headlamp aim too high (1.8)
- Fail** Nearside Rear rear brake binding (3.7.B.1)
- Advice** Offside Front Tyre worn close to the legal limit Inner edge. (4.1.E.1)
- Fail** Nearside Headlamp aim so that beam "kick up" is not visible on the screen (1.8.B.1)
- Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)
- Advice** Nearside Front Tyre worn close to the legal limit Inner edge. (4.1.E.1)



MOT #8	2016-10-21 08:13
---------------	------------------

MOT test number	750848503125
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2015-10-26 08:28
---------------	------------------

MOT test number	540646170928
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2014-10-29 10:47
---------------	------------------

MOT test number	175832304393
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2013-10-29 13:57
---------------	------------------

MOT test number	406872503344
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2013-10-29 11:22
---------------	------------------

MOT test number	678312903362
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Nearside Rear Seat belt insecurely fixed to the vehicles structure (5.2.1a)
-------------	---

MOT #3	2012-10-26 09:12
---------------	------------------

MOT test number	315080202313
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2011-10-31 15:15
---------------	------------------

MOT test number	667204601312
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #12010-10-14 08:30

MOT test number800137180275

Result

✓ Passed

- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice

Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
22 July 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	22 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-10-09
Last registration	2023-07-18
Complete history	See info



Registration #1	2009-10-09	14 mi
Registration #2	2010-10-14	30.075 mi
Registration #3	2011-10-31	64.099 mi
Registration #4	2012-10-26	89.124 mi
Registration #5	2013-10-29	107.583 mi
Registration #6	2013-10-29	107.600 mi
Registration #7	2014-10-29	131.590 mi
Registration #8	2015-10-26	144.999 mi
Registration #9	2016-10-21	150.844 mi
Registration #10	2017-10-18	159.426 mi
Registration #11	2017-10-19	159.462 mi
Registration #12	2018-10-19	160.000 mi
Registration #13	2019-10-19	160.000 mi
Registration #14	2020-10-19	160.000 mi
Registration #15	2021-10-19	160.000 mi
Registration #16	2022-10-19	160.000 mi
Registration #17	2023-10-19	160.000 mi
Registration #18	2024-10-19	160.000 mi
Registration #19	2025-10-19	160.000 mi
Registration #20	2026-10-19	160.000 mi
Registration #21	2027-10-19	160.000 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1722 mm
Height	2073 mm
Length	4253 mm
Wheel base	2583 mm
Kerb weight	1340 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	5996110