



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	IQ VVT-I IQ
Colour	White
Year of manufacture	2009
Top speed	93 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	91 Nm at 4.800 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1	
Date	2022-02-11
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-31
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	40
Total items failed	2

MOT #14	2023-10-25 12:29
MOT test number	176669054103
Result	✓ Passed
Next expiry date	2024-10-31
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13	2023-10-20 15:21
MOT test number	294327268524
Result	✗ Failed
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
MAJOR	Offside Rear Brake pipe excessively corroded (1.1.11 (c))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
MAJOR	Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

**MOT #12**

2022-10-26 15:56

MOT test number

950960482599

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #11

2021-10-07 08:47

MOT test number

252346677787

Result

✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened n/s o/s (1.1.14 (a) (ii))
- Advice** Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Inner sill has surface corrosion, not affecting vehicle structure/suspension mounting (Rear n/s o/s
- Advice** Rear Brake pipe corroded, covered in grease or other material n/s o/s (1.1.11 (c))
- Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn Perished (n/s o/s (5.1.2 (b) (i))

**MOT #10**

2020-10-15 08:45

MOT test number

596228366872

Result

✓ Passed

- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))
- Advice** Rear disc faces corroded
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement axle (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Exhaust center mtg insecure
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))
- Advice** Rear flex ferrules corroded
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement axle (5.3.4 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Underbody corroding

MOT #9

2019-11-01 10:04

MOT test number

340913377885

Result

✓ Passed

- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt
- Advice** Central Exhaust mounting defective (6.1.2 (a))



MOT #8	2019-11-01 10:04
MOT test number	359876342816
Result	✗ Failed
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Central Exhaust mounting defective (6.1.2 (a))

MOT #7	2018-03-08 10:37
MOT test number	420923388692
Result	✓ Passed
Advice	Rear child seat fitted
Advice	Front Tyre worn close to the legal limit n/s o/s (4.1.E.1)
Advice	Rear brake discs pitting/worn

MOT #6	2018-03-08 10:37
MOT test number	511140856083
Result	✗ Failed
Advice	Rear child seat fitted
Pass with rectification	Windscreen washer provides insufficient washer liquid (8.2.3)
Advice	Rear brake discs pitting/worn
Advice	Front Tyre worn close to the legal limit n/s o/s (4.1.E.1)

MOT #5	2017-03-21 17:56
MOT test number	583451014117
Result	✓ Passed



MOT #4	2015-10-14 08:32
MOT test number	190208787343
Result	✓ Passed
<div>AdviceBoth rear tyres splitting on outer shoulders.</div>	

MOT #3	2014-10-18 11:08
MOT test number	368911794240
Result	✓ Passed

MOT #2	2013-10-14 08:53
MOT test number	667127283231
Result	✓ Passed

MOT #1	2012-11-06 15:39
MOT test number	368221912307
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
31 October 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	31 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	SL59WXR
Plate since	2019-03-29
Current registration	SL59WXR
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-11-10
Last registration	2023-10-25
Complete history	See info



Registration #1	2009-11-10	13 mi
Registration #2	2012-11-06	15.346 mi
Registration #3	2013-10-14	22.251 mi
Registration #4	2014-10-18	30.504 mi
Registration #5	2015-10-14	33.688 mi
Registration #6	2017-03-21	39.443 mi
Registration #7	2018-03-08	46.233 mi
Registration #8	2018-03-08	46.233 mi
Registration #9	2019-03-20	55.277 mi
Registration #10	2019-03-20	55.277 mi
Registration #11	2019-03-20	55.277 mi
Registration #12	2019-03-20	55.277 mi
Registration #13	2019-03-20	55.277 mi
Registration #14	2019-03-20	55.277 mi
Registration #15	2019-03-20	55.277 mi
Registration #16	2019-03-20	55.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	845 kg
Max. allowed weight	1215 kg

Additional information

Fuel tank capacity	32 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1KR0827053