



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Grey
Year of manufacture	2009
Top speed	107 mph
0 - 60 mph	13.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	101 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	184 g/km
CO2 label	I



**MOT history**

MOT expiry date	2025-01-27
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	21
Total items failed	7

MOT #15 2024-01-22 16:45**MOT test number** 973825117267**Result** Passed**Next expiry date** 2025-01-27**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2023-01-21 11:09**MOT test number** 173717540739**Result** Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2022-01-13 11:46**MOT test number** 112073291950**Result** Passed

**MOT #12** 2021-01-28 17:26**MOT test number** 795950246526**Result** ✓ Passed**Advice** Corrosion on underbody, chassis, suspension and brake components**Advice** Engine covers/Under trays fitted**MOT #11** 2019-07-04 13:04**MOT test number** 278540479303**Result** ✓ Passed**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**MOT #10** 2019-07-03 09:25**MOT test number** 280901174558**Result** ✗ Failed**MAJOR** Offside Front Headlamp insecure (4.1.1 (c))**DANGEROUS** Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))**MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**MAJOR** Rear All direction indicators incorrect colour (4.4.3 (a))**DANGEROUS** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MAJOR** Offside Front Headlamp aim too high (4.1.2 (a))**MOT #9** 2018-07-24 13:17**MOT test number** 763521078351**Result** ✓ Passed**Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #8** 2017-10-27 15:24**MOT test number** 818699549762**Result** ✓ Passed**MOT #7** 2017-10-27 09:07**MOT test number** 910274584549**Result** ✗ Failed**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Offside Rear Anti-roll bar linkage cracked (2.4.G.1)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Rear Exhaust system not adequately supported (7.1.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #6** 2016-11-04 14:08**MOT test number** 488144274446**Result** ✓ Passed**Advice** Front brake discs in poor condition inner face**MOT #5** 2015-10-08 13:48**MOT test number** 168280219166**Result** ✓ Passed**Advice** Engine mounting deteriorated, but not resulting in excessive movement torque bush (6.1.D.1a)

**MOT #4** 2015-10-03 11:59**MOT test number** 654557483845**Result** ✗ Failed**Fail** Suspension arm has excessive play in a pin/bush front both (2.4.G.2)**Advice** Engine mounting deteriorated, but not resulting in excessive movement torque bush (6.1.D.1a)**Fail** Body insecure and dangerous to other road users heatshields (6.1.B.1b)**MOT #3** 2014-09-15 09:05**MOT test number** 707068554297**Result** ✓ Passed**MOT #2** 2013-08-28 07:57**MOT test number** 157660543245**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2012-08-16 09:17**MOT test number** 189849722208**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
27 January 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	27 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-09-01
Last registration	2024-01-22
Complete history	See info



Registration #1	2009-09-01	11 mi
Registration #2	2012-08-16	18.126 mi
Registration #3	2013-08-28	20.361 mi
Registration #4	2014-09-15	23.296 mi
Registration #5	2015-10-03	32.803 mi
Registration #6	2015-10-08	32.803 mi
Registration #7	2016-11-04	39.851 mi
Registration #8	2017-10-27	49.674 mi
Registration #9	2018-05-22	55.277 mi
Registration #10	2019-05-22	55.277 mi
Registration #11	2020-05-22	55.277 mi
Registration #12	2021-05-22	55.277 mi
Registration #13	2022-05-22	55.277 mi
Registration #14	2023-05-22	55.277 mi
Registration #15	2024-01-22	55.277 mi
Registration #16	2024-01-22	55.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1840 mm
Height	1501 mm
Length	4472 mm
Wheel base	2640 mm
Kerb weight	1340 kg
Max. allowed weight	1845 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9K16398