





report date: 2024-03-28

## General information

Make	TOYOTA
Model	IQ VVT-I IQ3
Colour	Black
Year of manufacture	2011
Top speed	106 mph
0 - 60 mph	11.8 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	97 BHP
Max. torque	123 Nm at 4.400 rpm
Engine capacity	1.329 сс
Cylinders	4
Fuel type	Petrol
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/13



# Internet history

### Entry 1

Date	2021-09-09
Pictures	1
Listing price	<u>View report</u>



source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-02-12
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	18
Total items failed	5

MOT #13	2024-02-13 09:30
MOT test number	815600575849
Result	<b>✓</b> Passed
Next expiry date	2025-02-12

MOT #12	2023-03-31 13:51
MOT test number	665383500170
Result	✓ Passed
Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #11	2022-04-04 15:19
MOT test number	220977030088
Result	✓ Passed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing On 3mm (5.2.3 (d) (ii))  Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 3/13



SG11KYP

report date: 2024-03-28

**MOT #10** 2022-04-04 09:31

**MOT test number** 316714285537

Result X Failed

Fail Nearside Front Suspension arm pin or bush excessively worn Bushing separating from metal (5.3.4 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Customer to monitor (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing On 3mm (5.2.3 (d) (ii))

**MOT #9** 2021-04-08 09:26

**MOT test number** 690234529259

Advice Nearside Front Tyre slightly damaged/cracking or perishing 175/60r15 (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing Needs doing ASAP. (5.2.3 (d) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8 2019-08-14 15:29

**MOT test number** 775261950275

**Result** ✓ Passed

MOT #7 2019-08-14 11:09

MOT test number 746858780168

**Result** X Failed

Fail Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Fail** Nearside Headlamp are incorrectly positioned (4.1.4 (a))

**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

CarCheck.co.uk page 4/13



MOT #6 2018-08-22 15:27

**MOT test number** 795631170762

**MOT #5** 2017-08-11 14:00

MOT test number 219242586922

**Result** 
✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2016-02-27 09:55

**MOT test number** 250131542339

Result \( \sqrt{Passed} \)

**Advice** Nearside Front Tyre starting to crack and perish

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened Inner face (3.5.1i)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

Advice Offside Front Tyre starting to crack and perish

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened Inner face (3.5.1i)

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

(2.4.G.2)

MOT #3 2015-03-02 10:08

**MOT test number** 695281665066

**Result** ✓ Passed

**MOT #2** 2014-02-28 09:03

**MOT test number** 316609454008

CarCheck.co.uk page 5/13



SG11KYP

report date: 2024-03-28

MOT #1

MOT test number

168269754468

Result

Pass with rectification

Offside Front Headlamp aim too low (1.8)

CarCheck.co.uk page 6/13



## Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	12 February 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

· ·		
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full research		DTA
***************************************		
***************************************		
*********		
***************************************		
	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		,
Current registration	NK SILE	
Plate since		
Current registration	UK NEZ	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



## Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 11/13



SG11KYP

report date: 2024-03-28

# Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-03-01
Last registration	2024-02-13
Complete history	See info



Registration #1	2011-03-01	24 mi
Registration #2	2014-02-28	27.802 mi
Registration #3	2015-03-02	31.093 mi
Registration #4	2016-02-27	34.057 mi
Registration #5	2017-08-11	44.151 mi
Registration #6	2018-08-22	57.938 mi
Registration #7	2019-08-14	59.721 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		0.00 es
Registration #12		0.00 44
Registration #13		

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



Car features

S0225	Air conditionin
S0295	
50482	
60501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



# Dimensions & weight

Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	955 kg
Max. allowed weight	1270 kg

# Additional information

Fuel tank capacity	32
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles 2

Engine number 1NR0274253