



PEUGEOT



BF55FUP

report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 ZEST 3
Colour	Silver
Year of manufacture	-
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.8 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-18
Pictures	27
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #21</b>	2023-03-01 11:30
<b>MOT test number</b>	610667300560
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-03-15
<b>Advice</b>	Front Anti-roll bar linkage ball joint has slight play both sides (5.3.4 (a) (i))

<b>MOT #20</b>	2023-03-01 11:30
<b>MOT test number</b>	606493419783
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
<b>Advice</b>	Front Anti-roll bar linkage ball joint has slight play both sides (5.3.4 (a) (i))

<b>MOT #19</b>	2022-03-09 11:25
<b>MOT test number</b>	107359719363
<b>Result</b>	✓ Passed
<b>Minor</b>	Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Minor</b>	Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

<b>MOT #18</b>	2022-03-09 11:25
<b>MOT test number</b>	442581834241
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
<b>Minor</b>	Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Minor</b>	Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #17** 2021-03-16 12:56**MOT test number** 114714837624**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2019-10-12 09:00**MOT test number** 207365712168**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2019-10-12 09:00**MOT test number** 106366305736**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #14** 2018-09-21 09:05**MOT test number** 693755912168**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2017-09-15 13:22**MOT test number** 851355291203**Result** ✓ Passed**Advice** Fuel tank strap corroded

**MOT #12** 2016-09-16 10:24**MOT test number** 196961222820**Result** ✓ Passed**Advice** Rear Fuel Tank strap corroded**Advice** Offside Rear Tyre worn close to the legal limit 3mm Tread Depth (4.1.E.1)**MOT #11** 2015-09-21 14:17**MOT test number** 874691973426**Result** ✓ Passed**Advice** Rear number plate slightly damaged**MOT #10** 2015-09-16 10:23**MOT test number** 241209387954**Result** ✗ Failed**Advice** Rear number plate slightly damaged**Fail** Offside Front Side repeater not working (1.4.A.2c)**MOT #9** 2014-09-20 09:58**MOT test number** 339983064205**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2013-09-06 11:24**MOT test number** 805759343288**Result** ✓ Passed**Notice** Exhaust corroded**Notice** Wipers starting to smear screen

**MOT #7** 2012-09-18 10:55**MOT test number** 357032462400**Result** ✓ Passed**Advice** Offside Inner Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2012-09-18 10:55**MOT test number** 849652462266**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Advice** Offside Inner Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2011-09-27 09:42**MOT test number** 267980171254**Result** ✓ Passed**MOT #4** 2011-09-26 11:31**MOT test number** 645809561286**Result** ✗ Failed**Fail** Offside Headlamp aim too low (1.8)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Driver's seat insecure (6.2.A.1)



MOT #3	2010-09-28 15:39
MOT test number	914521770235
Result	✓ Passed

MOT #2	2009-07-10 12:15
MOT test number	431881199112
Result	✓ Passed
<div>Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)</div>	

MOT #1	2008-07-15 11:54
MOT test number	374797698132
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-09-02
Last registration	2023-03-01
Complete history	<a href="#">See info</a>



Registration #1	2005-09-02	18 mi
Registration #2	2008-07-15	19.646 mi
Registration #3	2009-07-10	26.343 mi
Registration #4	2010-09-28	32.331 mi
Registration #5	2011-09-26	36.020 mi
Registration #6	2011-09-27	36.020 mi
Registration #7	2012-09-18	42.039 mi
Registration #8	2013-09-06	47.372 mi
Registration #9	2014-09-20	52.809 mi
Registration #10	2015-09-16	55.826 mi
Registration #11	2015-09-21	55.827 mi
Registration #12	2016-09-20	55.827 mi
Registration #13	2017-09-20	55.827 mi
Registration #14	2018-09-20	55.827 mi
Registration #15	2019-09-20	55.827 mi
Registration #16	2020-09-20	55.827 mi
Registration #17	2021-09-20	55.827 mi
Registration #18	2022-09-20	55.827 mi
Registration #19	2023-03-01	55.827 mi
Registration #20		
Registration #21		
Registration #22		

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FSR95200647