





report date: 2024-03-29

#### General information

Make	FIAT
Model	500L POP STAR
Colour	Red
Year of manufacture	2014
Top speed	111 mph
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	95 BHP
Max. torque	127 Nm at 4.500 rpm
Engine capacity	1.368 сс
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-29

### Internet history

#### Entry 2

Date 2021-10-28

Pictures 6

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-10-27
Pictures	6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT I	nistory
-------	---------

MOT expiry date	2024-10-30
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	16
Total items failed	5

MOT #9	2023-10-31 11:05
MOT test number	263116839944
Result	<b>✓</b> Passed
Next expiry date	2024-10-30

MOT #8	2022-10-14 11:27
MOT test number	402643258435
Result	✓ Passed

MOT #7		2021-10-15 13:00
MOT test	number	837528278914
Result		✓ Passed
Advice	Central Front Exhaust has a minor leak of exhaust gases front flex (6.1.2 (a))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #6	2020-02-08 10:02
MOT test number	615734634234
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



Advice

MM63APZ

report date: 2024-03-29

MOT #5

MOT test number

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #4** 2019-02-06 12:25 **MOT** test number 604772623317 Result × Failed Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a)) Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Pass with rectification Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a)) Pass with rectification Nearside Front Headlamp aim too low (4.1.2 (a)) **Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT test number

Result

Advice Nearside Rear Nail in tyre x2

Advice Items removed from driver's view prior to test air-freshner

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

Result

Advice Nearside Rear Nail in tyre x2

Pass with rectification Nearside Rear Seat belt locking mechanism does not secure or release (5.2.5a)

Advice Items removed from driver's view prior to test air-freshner

 MOT #1
 2017-02-17 12:53

 MOT test number
 910188411412

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 November
Days left	187
MOT expiry date	30 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

$\sim$	
Owner	history
OWITCE	HIISCOLY

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>I</u>	
THE PARTY OF THE P	
***************************************	
THE PARTY OF THE P	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	UK ZIS
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-02-18
Last registration	2023-10-31
Complete history	See info



Registration #1	2014-02-18	9 mi
Registration #2	2017-02-17	17.069 mi
Registration #3	2018-02-13	26.283 mi
Registration #4	2018-02-13	26.283 mi
Registration #5	2019-02-06	36.822 mi
Registration #6	2019-02-06	36.822 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

# Safety ratings

NCAP rating	****
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	2018 mm
Height	1667 mm
Length	4147 mm
Wheel base	2612 mm
Kerb weight	1245 kg
Max. allowed weight	1805 kg

## Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number 4019969