



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	JETTA TDI SE 5STR
Colour	Blue
Year of manufacture	2008
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-04
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2025-04-26
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	18
Total items failed	7

MOT #18	2024-04-22 10:12
MOT test number	122383218950
Result	✓ Passed
Next expiry date	2025-04-26

MOT #17	2024-04-22 10:12
MOT test number	606891914873
Result	✗ Failed
Pass with rectification Offside Registration plate lamp likely to become detached (4.7.1 (c) (ii))	

MOT #16	2023-04-03 09:20
MOT test number	634659722510
Result	✓ Passed

MOT #15	2022-04-27 10:48
MOT test number	507846253086
Result	✓ Passed

MOT #14	2022-04-27 10:48
MOT test number	556404267661
Result	✗ Failed
Pass with rectification Offside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))	

**MOT #13**

2021-01-04 14:23

MOT test number

559127985364

Result

✓ Passed

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened Lipped both sides (1.1.14 (a) (ii))

MOT #12

2020-01-09 14:44

MOT test number

749480152301

Result

✓ Passed

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

Advice

Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))

MOT #11

2019-01-11 10:46

MOT test number

723867112610

Result

✓ Passed

Advice

Rear Tyre slightly damaged/cracking or perishing both sides (edges perished) (5.2.3 (d) (ii))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

MOT #10

2019-01-10 12:45

MOT test number

334324378863

Result

✗ Failed

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

Fail

Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail

Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice

Rear Tyre slightly damaged/cracking or perishing both sides (edges perished) (5.2.3 (d) (ii))

**MOT #9** 2018-01-15 15:09**MOT test number** 659563686121**Result** ✓ Passed

- Advice** Both sides rear tyre inner edge slightly perished
- Advice** Rear Brake pad(s) wearing thin both sides (3.5.1g)
- Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)
- Advice** Under-trays fitted obscuring some underside components
- Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Nearside Front Upper Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

MOT #8 2017-01-16 15:40**MOT test number** 424289535189**Result** ✓ Passed

- Advice** Tyre worn close to the legal limit both front (4.1.E.1)

MOT #7 2016-01-05 15:46**MOT test number** 906107310904**Result** ✓ Passed**MOT #6** 2015-01-15 13:17**MOT test number** 155425015415**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components

MOT #5 2014-01-10 10:36**MOT test number** 556320414095**Result** ✓ Passed

**MOT #4** 2014-01-09 12:09**MOT test number** 147129104012**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #3** 2013-01-08 11:25**MOT test number** 949898403080**Result** ✓ Passed**MOT #2** 2012-01-24 14:23**MOT test number** 329664622068**Result** ✓ Passed**MOT #1** 2011-01-24 11:05**MOT test number** 758074121030**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
26 April 2025

Tax status	Valid until 1 June
Days left	32
MOT expiry date	26 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-01-30
Last registration	2024-04-22
Complete history	See info



Registration #1	2008-01-30	6 mi
Registration #2	2011-01-24	20.775 mi
Registration #3	2012-01-24	30.156 mi
Registration #4	2013-01-08	38.579 mi
Registration #5	2014-01-09	47.975 mi
Registration #6	2014-01-10	47.994 mi
Registration #7	2015-01-15	57.274 mi
Registration #8	2016-01-05	66.547 mi
Registration #9	2017-01-16	77.833 mi
Registration #10	2018-01-15	88.148 mi
Registration #11	2019-01-20	98.463 mi
Registration #12	2020-01-20	108.778 mi
Registration #13	2021-01-20	119.093 mi
Registration #14	2022-01-20	129.408 mi
Registration #15	2023-01-20	139.723 mi
Registration #16	2024-01-20	150.038 mi
Registration #17	2025-01-20	160.353 mi
Registration #18	2026-01-20	170.668 mi
Registration #19	2027-01-20	180.983 mi
Registration #20	2028-01-20	191.298 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BXE A27658