





report date: 2024-03-28

## General information

Make	LAND ROVER
Model	FREELANDER SD4 GS
Colour	White
Year of manufacture	2014
Top speed	118 mph
0 - 100 km/h	9.5 seconds
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	140 kW / 191 HP / 190 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I



CarCheck.co.uk page 1/12



## Internet history

### Entry 2

Date	2021-09-17
Pictures	20
Listing price	View report









source: cargurus.co.uk

#### Entry 1

Date	2021-09-10
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-10-10
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	12
Total items failed	2

MOT #10	2023-10-02 15:00
MOT test number	237647324763
Result	<b>✓</b> Passed
Next expiry date	2024-10-10

MOT #9		2023-10-02 15:00
MOT test number		305019878890
Result		<b>×</b> Failed
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))	

MOT #8	2022-09-14 15:28
MOT test number	830421455646
Result	<b>√</b> Passed
MOT #7	2021-10-11 06:34
MOT test number	294075572278
Result	<b>√</b> Passed
MOT #6	2021-01-21 09:28
MOT test number	949901074366
Result	.✓ Passed

CarCheck.co.uk page 3/12



LY63HBL

report date: 2024-03-28

MOT #5		2020-01-20 15:23
MOT test	number	943386783025
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4		2020-01-20 11:49
MOT test	number	779414701574
Result		🗙 Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Fail</b> No	earside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3	3 (g) (ii))

MOT #3		2019-01-16 12:43
MOT test	number	642026729051
Result		✓ Passed
Advice	Engine cover fitted obscuring some components	
Advice	Under tray fitted obscuring some components	

MOT #2		2018-01-16 09:31
MOT test	number	178242620158
Result		<b>✓</b> Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Under tray fitted obsecuring some components	
Advice	Engine cover fitted obsecuring some components	

CarCheck.co.uk page 4/12



MOT #1 2017-02-08 09:20

**MOT test number** 281643673048

**Result** ✓ Passed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	10 October 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



## Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date
Category

Type

Damage 2

**Date** 

Category

**Type** 



#### Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

*	
For how long did the current and previous owner(s) have this LAND ROVER? How many o ROVER have? Check it in the premium report and see all owner registrations. Download to	
***************************************	
THE PARTY OF THE P	
***************************************	
	More info >
Plate changes  See in this check if this LAND ROVER had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIL
Plate since	
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-01-17
Last registration	2023-10-02
Complete history	See info



Registration #1	2014-01-17	24 mi
Registration #2	2017-02-08	19.101 mi
Registration #3	2018-01-16	21.742 mi
Registration #4	2019-01-16	24.923 mi
Registration #5	2020-01-20	27.711 mi
Registration #6	2020-01-20	27.763 mi
Registration #7	2021-01-21	29.385 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		D.777 es

More info >

CarCheck.co.uk page 11/12



## Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2005 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1745 kg
Max. allowed weight	2505 kg

## Additional information

Fuel tank capacity	68 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	DZ784181354224DT

CarCheck.co.uk page 12/12