



report date: 2024-03-28

General information

Make	FORD
Model	FOCUS TITANIUM 136PS
Colour	Silver
Year of manufacture	2009
Top speed	124 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-01-30
Pictures	9
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-04-16
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	34
Total items failed	3

MOT #14	2023-04-17 10:57
MOT test number	126365783948
Result	✓ Passed
Next expiry date	2024-04-16
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Bonnet open warning permanently on
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #13**

2023-04-14 11:00

**MOT test number**

926020868337

**Result**

✗ Failed

**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Bonnet open warning permanently on**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12**

2021-11-26 10:39

**MOT test number**

438033785740

**Result**

✓ Passed

**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Tyre worn close to legal limit/worn on edge Both front and also perished (5.2.3 (e))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #11**

2020-07-22 09:24

**MOT test number**

265394363487

**Result**

✓ Passed

**MOT #10**

2019-04-08 12:00

**MOT test number**

948202650712

**Result**

✓ Passed



<b>MOT #9</b>	2018-04-10 09:13
<b>MOT test number</b>	443522101820
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

<b>MOT #8</b>	2017-04-10 14:45
<b>MOT test number</b>	810296784531
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Advice</b>	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Advice</b>	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Advice</b>	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

<b>MOT #7</b>	2017-04-05 09:35
<b>MOT test number</b>	310586047345
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Advice</b>	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Fail</b>	Offside Front coil spring broken (2.4.C.1a)
<b>Advice</b>	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Advice</b>	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

<b>MOT #6</b>	2016-03-17 15:09
<b>MOT test number</b>	375952117008
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2015-04-08 13:12**MOT test number** 679988995057**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-05-20 13:47**MOT test number** 878570544109**Result** ✓ Passed**MOT #3** 2013-05-17 13:13**MOT test number** 859287433131**Result** ✓ Passed**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**MOT #2** 2012-05-18 12:58**MOT test number** 546439432121**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #1** 2012-05-18 12:58**MOT test number** 545679432113**Result** ✗ Failed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Pass with rectification** Offside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>EK09PLU</b>
Plate since	2019-03-28
Current registration	<b>EK09PLU</b>
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-05-20
Last registration	2023-04-17
Complete history	<a href="#">See info</a>



Registration #1	2009-05-20	27 mi
Registration #2	2012-05-18	27.568 mi
Registration #3	2013-05-17	36.071 mi
Registration #4	2014-05-20	46.421 mi
Registration #5	2015-04-08	59.399 mi
Registration #6	2016-03-17	71.304 mi
Registration #7	2017-04-05	73.672 mi
Registration #8	2017-04-10	73.686 mi
Registration #9	2018-05-20	75.277 mi
Registration #10	2019-05-20	75.277 mi
Registration #11	2020-05-20	75.277 mi
Registration #12	2021-05-20	75.277 mi
Registration #13	2022-05-20	75.277 mi
Registration #14	2023-05-20	75.277 mi
Registration #15	2024-05-20	75.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2648 mm
Kerb weight	1436 kg
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	9M69724