



report date: 2024-03-28

General information

Make	NISSAN
Model	ALMERA SE
Colour	Black
Year of manufacture	2004
Top speed	110 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	97 BHP
Max. torque	136 Nm at 4.000 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	160 g/km
CO2 label	G





MOT history

MOT expiry date	2024-11-18
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	58
Total items failed	25

**MOT #23**

2023-10-20 13:46

MOT test number

314688604659

Result

✓ Passed

Next expiry date

2024-11-18

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 195/55/16 low tread and heavy inner edge wear (5.2.3 (e))

Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Nearside Rear Nail in tyre

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Rear Nail in tyre

Advice Oil leak, but not excessive (8.4.1 (a) (i))



MOT #22	2023-10-16 10:25
MOT test number	601192085471
Result	✗ Failed

Advice Offside Rear Nail in tyre

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Fail Offside Front Headlamp aim too low (4.1.2 (a))

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Front Headlamp insecure (4.1.1 (c))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Nearside Front Bumper insecure (6.1.4 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))

Advice Nearside Rear Nail in tyre

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Fail Offside Front Headlamp are incorrectly positioned (4.1.4 (a))

Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 195/55/16 low tread and heavy inner edge wear (5.2.3 (e))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #21**

2022-11-17 16:13

MOT test number

131632332006

Result

✓ Passed

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #20**

2022-11-17 16:13

MOT test number

155923943690

Result

✗ Failed

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Pass with rectification** Offside Rear Stop lamp(s) all not working (4.3.1 (a) (iii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #19**

2021-11-19 12:21

MOT test number

912806032843

Result

✓ Passed

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #18** 2021-11-19 12:21**MOT test number** 647838309299**Result** ✗ Failed**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MOT #17** 2020-10-09 16:45**MOT test number** 876332456781**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #16** 2020-10-09 15:53**MOT test number** 703283668953**Result** ✗ Failed**Fail** Offside Headlamp insecure (4.1.1 (c))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #15** 2019-04-01 08:16**MOT test number** 963207366172**Result** ✓ Passed

**MOT #14** 2018-04-03 10:19**MOT test number** 780207552314**Result** ✓ Passed**Advice** Items removed from driver's view prior to test PHONE MOUNT.**MOT #13** 2017-03-25 10:23**MOT test number** 650231435586**Result** ✓ Passed**MOT #12** 2016-03-21 16:27**MOT test number** 476143531776**Result** ✓ Passed**Advice** Reverse lamp not working.**MOT #11** 2016-03-21 12:27**MOT test number** 437728804535**Result** ✗ Failed**Advice** Reverse lamp not working.**Fail** Nearside Rear Rear position lamp(s) adversely affected by the operation of another lamp all three stop lights operate when tail lights on. (1.1.A.3f)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Offside Rear Rear position lamp(s) adversely affected by the operation of another lamp all three stop lights operate when tail lights on. (1.1.A.3f)**MOT #10** 2015-04-13 13:21**MOT test number** 256403405148**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #9** 2015-03-31 17:54**MOT test number** 188290295051**Result** ✗ Failed

- Fail** Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)
- Fail** Nearside Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)
- Fail** Nearside Front front brake excessively fluctuating (3.7.B.3)
- Fail** Centre Rear Stop lamp remains on when the brakes are released (1.2.1e)
- Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Fail** Front position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)
- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Fail** Nearside Front wheel bearing rough when rotated (2.5.A.2)
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Offside Rear Stop lamp remains on when the brakes are released (1.2.1e)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #8 2014-01-28 15:30**MOT test number** 216588924090**Result** ✓ Passed**MOT #7** 2013-02-19 15:16**MOT test number** 427670153054**Result** ✓ Passed**MOT #6** 2012-03-02 15:37**MOT test number** 987032862027**Result** ✓ Passed

- Notice** Rust build up on rear discs . efficiency ok .

**MOT #5** 2011-02-16 16:39**MOT test number** 517347041082**Result** ✓ Passed**Notice** Rear discs going rusty .**MOT #4** 2010-02-24 09:31**MOT test number** 544115650087**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2009-03-09 16:17**MOT test number** 743598669061**Result** ✓ Passed**MOT #2** 2008-03-12 13:00**MOT test number** 784632078054**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2007-03-13 12:40**MOT test number** 594132777085**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
18 November 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	18 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-03-04
Last registration	2023-10-20
Complete history	See info



Registration #1	2004-03-04	6 mi
Registration #2	2007-03-13	30.707 mi
Registration #3	2008-03-12	36.253 mi
Registration #4	2009-03-09	40.168 mi
Registration #5	2010-02-24	44.890 mi
Registration #6	2011-02-16	45.311 mi
Registration #7	2012-03-02	45.844 mi
Registration #8	2013-02-19	48.415 mi
Registration #9	2014-01-28	51.289 mi
Registration #10	2015-03-31	60.537 mi
Registration #11	2015-04-13	60.537 mi
Registration #12	2016-03-21	63.978 mi
Registration #13	2016-03-21	55.000 mi
Registration #14	2016-03-21	55.000 mi
Registration #15	2016-03-21	55.000 mi
Registration #16	2016-03-21	55.000 mi
Registration #17	2016-03-21	55.000 mi
Registration #18	2016-03-21	55.000 mi
Registration #19	2016-03-21	55.000 mi
Registration #20	2016-03-21	55.000 mi
Registration #21	2016-03-21	55.000 mi
Registration #22	2016-03-21	55.000 mi
Registration #23	2016-03-21	55.000 mi
Registration #24	2016-03-21	55.000 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1179 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	267070