



report date: 2024-03-29

General information

Make	KIA
Model	CEED 3
Colour	Silver
Year of manufacture	2013
Top speed	121 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	133 BHP
Max. torque	164 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	57.7 mpg
Consumption combined	46.3 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-04-21
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	26
Total items failed	4

MOT #14	2024-04-16 16:09
MOT test number	152058898604
Result	✓ Passed
Next expiry date	2025-04-21
Advice	Rear rear suspension and sub-frame corroded

MOT #13	2024-04-16 12:01
MOT test number	447616807160
Result	✗ Failed
Advice	Rear rear suspension and sub-frame corroded
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge 205/55/16 (5.2.3 (e))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2023-03-28 15:56

**MOT test number**

834694502867

**Result**

✓ Passed

- Advice** Corrosion on front and rear suspension components
- Advice** Underfloor panels fitted
- Advice** Front and rear inner arch liners fitted
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #11**

2023-03-28 11:08

**MOT test number**

888583194235

**Result**

✗ Failed

- Fail** Offside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Corrosion on front and rear suspension components
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Underfloor panels fitted
- Advice** Front and rear inner arch liners fitted

**MOT #10**

2022-04-20 15:33

**MOT test number**

848825395136

**Result**

✓ Passed

**MOT #9**

2022-04-20 09:10

**MOT test number**

373231500710

**Result**

✗ Failed

- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8** 2021-04-22 09:58**MOT test number** 468441534379**Result** ✓ Passed**MOT #7** 2020-06-01 08:35**MOT test number** 436520253398**Result** ✓ Passed**MOT #6** 2019-06-06 08:54**MOT test number** 268267929506**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2018-06-01 13:42**MOT test number** 929472114803**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4** 2018-06-01 09:04**MOT test number** 649028956209**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))**MOT #3** 2017-06-05 09:21**MOT test number** 560422223983**Result** ✓ Passed**Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**MOT #2** 2016-06-07 11:15**MOT test number** 626735345368**Result** ✓ Passed**MOT #1** 2016-01-22 16:45**MOT test number** 942768100825**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
21 April 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	21 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>WG62PFF</b>
Plate since	2019-03-29
Current registration	<b>WG62PFF</b>
Plate since	2019-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-01-05
Last registration	2024-04-16
Complete history	<a href="#">See info</a>



Registration #1	2013-01-05	6 mi
Registration #2	2016-01-22	15.552 mi
Registration #3	2016-06-07	16.808 mi
Registration #4	2017-06-05	27.684 mi
Registration #5	2018-06-01	38.825 mi
Registration #6	2018-06-01	38.825 mi
Registration #7	2019-06-06	48.155 mi
Registration #8	2020-06-01	55.796 mi
Registration #9	2020-06-01	55.796 mi
Registration #10	2020-06-01	55.796 mi
Registration #11	2020-06-01	55.796 mi
Registration #12	2020-06-01	55.796 mi
Registration #13	2020-06-01	55.796 mi
Registration #14	2020-06-01	55.796 mi
Registration #15	2020-06-01	55.796 mi
Registration #16	2020-06-01	55.796 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	88%
Pedestrian	61%
Safety systems	86%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1780 mm
Height	1470 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1421 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	G4FDDZ706991