



report date: 2024-03-28

General information

Make	AUDI
Model	A4 TDI QUATTRO DPF S LINE
Colour	White
Year of manufacture	2011
Top speed	140 mph
0 - 100 km/h	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	105 kW / 143 HP / 170 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	145 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-15
Pictures	46
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-25
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	31
Total items failed	1

MOT #15	2023-05-26 16:23
MOT test number	567312647713
Result	✓ Passed
Next expiry date	2024-05-25
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))

MOT #14	2023-05-26 13:07
MOT test number	417715051762
Result	✗ Failed
MAJOR	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
MAJOR	Electronic braking system warning device indicates a fault (1.7 (b))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))

MOT #13	2022-09-26 14:52
MOT test number	727597065846
Result	✓ Passed

**MOT #12**

2022-09-23 11:48

MOT test number

780975686613

Result**✗ Failed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Front Steering column flexible coupling is excessively deteriorated (2.2.2 (c))**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Front Lower Suspension arm pin or bush excessively worn both sides (5.3.4 (a) (i))**MOT #11**

2021-09-15 12:33

MOT test number

958893298775

Result**✓ Passed****Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2020-09-23 09:12

MOT test number

402176549224

Result**✓ Passed****MOT #9**

2019-10-11 08:15

MOT test number

437695311434

Result**✓ Passed****Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing has a cut (5.2.3 (d) (ii))

**MOT #8** 2018-09-21 15:48**MOT test number** 488252330089**Result** ✓ Passed**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #7** 2018-09-21 10:21**MOT test number** 590588046917**Result** ✗ Failed**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2017-10-04 09:58**MOT test number** 141492368215**Result** ✓ Passed**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #5** 2016-10-13 12:52**MOT test number** 727491455220**Result** ✓ Passed**MOT #4** 2016-05-16 09:54**MOT test number** 894377959188**Result** ✓ Passed**Advice** Cuts in n/s/f tyre side wall**Advice** Engine cover&under tray fitted**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #3** 2016-05-09 09:36**MOT test number** 711862340763**Result** ✗ Failed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Engine cover&under tray fitted**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Cuts in n/s/f tyre side wall**MOT #2** 2015-05-09 13:04**MOT test number** 246679525424**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #1** 2014-05-12 13:37**MOT test number** 359822934144**Result** ✓ Passed**Notice** Nearside outer sill damaged**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
25 May 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	25 May 2024
Full MOT history	See MOT history

Tax calculation


Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-05-13
Last registration	2023-05-26
Complete history	See info



Registration #1	2011-05-13	10 mi
Registration #2	2014-05-12	41.942 mi
Registration #3	2015-05-09	51.813 mi
Registration #4	2016-05-09	65.925 mi
Registration #5	2016-05-16	66.121 mi
Registration #6	2016-10-13	70.857 mi
Registration #7	2017-10-04	84.950 mi
Registration #8	2018-09-21	99.420 mi
Registration #9	2018-09-21	99.420 mi
Registration #10	2019-05-20	99.420 mi
Registration #11	2019-05-20	99.420 mi
Registration #12	2019-05-20	99.420 mi
Registration #13	2019-05-20	99.420 mi
Registration #14	2019-05-20	99.420 mi
Registration #15	2019-05-20	99.420 mi
Registration #16	2019-05-20	99.420 mi
Registration #17	2019-05-20	99.420 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	84%
Pedestrian	39%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1826 mm
Height	1427 mm
Length	4717 mm
Wheel base	2808 mm
Kerb weight	1555 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	CAH 203629