



report date: 2024-03-28

General information

Make	MAZDA
Model	MX-5 I
Colour	Black
Year of manufacture	2006
Top speed	130 mph
0 - 60 mph	7.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	166 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	183 g/km
CO2 label	I





MOT history

MOT expiry date	2021-08-06
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	21
Total items failed	5

MOT #16 2020-08-04 10:49

MOT test number 612840845691

Result ✓ Passed

Next expiry date 2021-08-06

Minor Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #15 2019-07-08 09:29

MOT test number 551074993090

Result ✓ Passed

Minor Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2018-08-07 09:08**MOT test number** 750181801803**Result** ✓ Passed**Minor** Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2017-07-15 08:56**MOT test number** 604333579192**Result** ✓ Passed**MOT #12** 2016-07-13 09:22**MOT test number** 991868413027**Result** ✓ Passed**MOT #11** 2015-07-10 15:53**MOT test number** 276761795165**Result** ✓ Passed**MOT #10** 2015-07-10 10:37**MOT test number** 947621995145**Result** ✗ Failed**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #9** 2014-07-16 15:03**MOT test number** 697877694197**Result** ✓ Passed

**MOT #8** 2013-07-16 15:59**MOT test number** 727327093132**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2013-07-16 15:59**MOT test number** 368347693148**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2012-09-11 11:40**MOT test number** 205735052258**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2011-08-17 10:14**MOT test number** 347469521421**Result** ✓ Passed



MOT #4	2011-08-11 16:05
MOT test number	446103321237
Result	✗ Failed
Fail	Offside Front Anti-roll bar linkage rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)

MOT #3	2010-08-09 16:56
MOT test number	862561920287
Result	✓ Passed

MOT #2	2009-07-01 15:30
MOT test number	863022389122
Result	✓ Passed
Notice	Nearside side repeater lens slight damage

MOT #1	2009-07-01 09:05
MOT test number	201732089118
Result	✗ Failed
Fail	Nearside Side repeater incomplete (1.5.A1b)



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-06-30
Last registration	2020-08-04
Complete history	See info



Registration #1	2006-06-30	17 mi
Registration #2	2009-07-01	10.544 mi
Registration #3	2009-07-01	10.544 mi
Registration #4	2010-08-09	16.757 mi
Registration #5	2011-08-11	18.337 mi
Registration #6	2011-08-17	18.357 mi
Registration #7	2012-09-11	19.570 mi
Registration #8	2013-07-16	20.898 mi
Registration #9	2013-07-16	20.898 mi
Registration #10	2013-07-16	20.898 mi
Registration #11	2013-07-16	20.898 mi
Registration #12	2013-07-16	20.898 mi
Registration #13	2013-07-16	20.898 mi
Registration #14	2013-07-16	20.898 mi
Registration #15	2013-07-16	20.898 mi
Registration #16	2013-07-16	20.898 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1720 mm
Height	1245 mm
Length	3995 mm
Wheel base	2330 mm
Kerb weight	1080 kg
Max. allowed weight	1355 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	LF 654000