





report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Blue
Year of manufacture	2008
Top speed	129 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Sequential

Engine & fuel consumption

Power	145 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	184 g/km
CO2 label	1



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2021-11-12

Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-11-10
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-05-14
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	18
Total items failed	3

MOT #14		2023-04-26 08:38
MOT test	number	441655769812
Result		✓ Passed
Next expi	ry date	2024-05-14
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Coil spring mounting corroded but not seriously weakened (5.3.1 (b)	(i))
Advice	Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #13	2022-05-09 08:08
MOT test number	632769839531
Result	✓ Passed
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	

CarCheck.co.uk page 3/12



Result

DA08DKJ report date: 2024-03-28

Passed

MOT #12 2021-05-06 09:20

MOT test number 989372906896

Result \(\sqrt{Passed}

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #11 2020-05-05 14:48

MOT test number 477237933115

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2020-05-04 09:22

MOT test number 129946812231

Result X Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #9 2019-05-07 09:36

MOT test number 642223840302

Result \(\sqrt{Passed} \)

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8 2018-05-09 10:41

MOT test number 526608201019

Result ✓ Passed

CarCheck.co.uk page 4/12



MOT #1

Result

MOT test number

DA08DKJ

report date: 2024-03-28

2011-05-12 18:00

298132031133

✓ Passed

MOT #7		2017-05-09 10:39
MOT test	number	552873040370
Result		✓ Passed
MOT #6		2016-05-11 10:58
MOT test	number	448260809177
Result		✓ Passed
MOT #5		2015-05-05 11:37
MOT test	number	198715425121
Result		✓ Passed
MOT #4		2014-05-12 09:38
MOT test	number	689912334175
Result		✓ Passed
MOT #3		2012 05 00 11:01
MOT #5	number	2013-05-08 11:01 735878423128
Result	Tullipei	✓ Passed
Notice	Front discs ,inner surfaces slightly worn	•
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	
MOT #2		2012-05-08 12:14
MOT test	number	817099222130
Result		✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	14 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	T
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

· · · · · · · · · · · · · · · · · · ·		
For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		λ R

	More info	>
Plate changes See in this check if this JAGUAR had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	NK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-05-14
Last registration	2023-04-26
Complete history	See info



Registration #1	2008-05-14	17 mi
Registration #2	2011-05-12	18.124 mi
Registration #3	2012-05-08	21.547 mi
Registration #4	2013-05-08	26.046 mi
Registration #5	2014-05-12	31.608 mi
Registration #6	2015-05-05	36.835 mi
Registration #7	2016-05-11	41.978 mi
Registration #8	2017-05-09	46.587 mi
Registration #9	2018-05-09	49.822 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		0.00 44
Registration #17		

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1395 mm
Length	4672 mm
Wheel base	2710 mm
Max. allowed weight	2065 kg

Additional information

Fuel tank capacity	61
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	080212203227BG

CarCheck.co.uk page 12/12