





report date: 2024-03-28

General information

Make	RENAULT
Model	CLIO DYNAMIQUE MEDIANAV ENERGY TCE S/S
Colour	Black
Year of manufacture	2013
Top speed	113 mph
0 - 60 mph	12.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	135 Nm at 2.500 rpm
Engine capacity	899 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-01-21

Pictures 36

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2023-07-11
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	7
Total items failed	8

MOT #8	2022-07-12 15:17
MOT test number	153553578132
Result	✓ Passed
Next expiry date	2023-07-11

MOT #7 2022-05-04 14:13 **MOT** test number 858255279881 Result × Failed Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i)) Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) **Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i)) **Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) **Advice** Under covers fitted Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail

MOT #6	2021-03-22 09:20
MOT test number	606385759746
Result	✓ Passed

CarCheck.co.uk page 3/11



(b) (ii))

NJ63ZGA report date: 2024-03-28

MOT #5

MOT test number

Fesult

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2018-09-06 10:56 **MOT** test number 100208717992 Result ✓ Passed **MOT** #3 2018-09-06 10:56 **MOT test number** 798852465374 Result ★ Failed Pass with rectification Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) **Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Pass with rectification** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4

MOT #2

MOT test number

Result

2017-09-28 13:01

314946340899

✓ Passed

MOT #1

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/11



Tax & MOT check



Х мот

Tax expired: 1 July 2023 Expired: 11 July 2023

Tax status	Expired at 1 July 2023
Days left	302 days too late
MOT expiry date	11 July 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



NJ63ZGA

report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



_	
Owner	hictory
OWITEL	HIISLUHV

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	NIE SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2013-09-30
Last registration	2022-07-12
Complete history	See info



Registration #1	2013-09-30	12 mi
Registration #2	2016-09-28	12.336 mi
Registration #3	2017-09-28	16.619 mi
Registration #4	2018-09-06	20.753 mi
Registration #5	2018-09-06	20.753 mi
110910111111111111111111111111111111111	2010 03 00	
Registration #6	2020 05 00	11.777 ea
		11.777 es
Registration #6		11.777 ea 11.777 ea 11.777 ea
Registration #6 Registration #7		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
50567	
S0569	

Safety ratings

NCAP rating	****
Adult	88%
Children	89%
Pedestrian	66%
Safety systems	99%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1732 mm
Height	1488 mm
Length	4062 mm
Wheel base	2589 mm
Kerb weight	980 kg
Max. allowed weight	1588 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

Engine number U054847