



HYUNDAI



**BL640WK**

report date: 2024-03-28

## General information

Make	HYUNDAI
Model	IX35 CRDI SE
Colour	Black
Year of manufacture	2015
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2025-03-04
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	19
Total items failed	9

MOT #11	2024-03-05 09:01
MOT test number	966741860683
Result	✓ Passed
Next expiry date	2025-03-04

MOT #10	2023-03-03 12:06
MOT test number	701453428659
Result	✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #9	2023-03-01 15:44
MOT test number	326996972164
Result	✗ Failed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Fail	Rear fog lamp not working (4.5.1 (a) (ii))
Advice	Parking brake lever has little reserve travel, adjustment/ inspection required

MOT #8	2022-03-01 10:25
MOT test number	164345641381
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #7** 2021-03-04 09:39**MOT test number** 512007453337**Result** ✓ Passed**MOT #6** 2021-03-02 14:20**MOT test number** 395989689176**Result** ✗ Failed

- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2020-09-02 15:58**MOT test number** 499397677045**Result** ✗ Failed

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #4** 2020-01-04 10:01**MOT test number** 931441272953**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2019-01-05 09:08**MOT test number** 981040299567**Result** ✓ Passed**Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))**Advice** Offside Rear Nail in tyre**MOT #2** 2017-12-30 17:13**MOT test number** 730281459498**Result** ✓ Passed



MOT #1 2017-12-30 09:19

MOT test number 914496002201

Result ✗ Failed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Fail** Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
4 March 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	4 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-01-12
Last registration	2024-03-05
Complete history	<a href="#">See info</a>



Registration #1	2015-01-12	22 mi
Registration #2	2017-12-30	28.054 mi
Registration #3	2017-12-30	28.054 mi
Registration #4	2019-01-05	38.613 mi
Registration #5	2020-01-04	49.185 mi
Registration #6	2020-09-02	53.671 mi
Registration #7	2020-09-02	53.671 mi
Registration #8	2020-09-02	53.671 mi
Registration #9	2020-09-02	53.671 mi
Registration #10	2020-09-02	53.671 mi
Registration #11	2020-09-02	53.671 mi
Registration #12	2020-09-02	53.671 mi
Registration #13	2020-09-02	53.671 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D4FDFZ359220