



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM SE BLUE DRIVE
Colour	Silver
Year of manufacture	2015
Top speed	126 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	440 Nm at 2.750 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	46.3 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history


Entry 6

Date	2023-06-05
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 5

Date	2023-05-24
Pictures	50
Listing price	View report



source: [cargurus.co.uk](#)

Entry 4


Date	2023-03-09
Pictures	29
Listing price	View report



source: [cargurus.co.uk](#)

Entry 3

Date	2023-03-09
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date	2021-06-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

Entry 1

Date	2021-05-22
Pictures	0
Listing price	View report

source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-19
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	14
Total items failed	4

MOT #10	2024-02-19 17:38
MOT test number	814734642940
Result	✓ Passed
Next expiry date	2025-02-19

MOT #9	2023-02-20 14:58
MOT test number	519603385239
Result	✓ Passed

MOT #8	2022-06-06 15:42
MOT test number	530423411230
Result	✓ Passed

MOT #7	2022-06-06 09:54
MOT test number	316896761234
Result	✗ Failed
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #6**

2021-06-17 08:19

MOT test number

606245297315

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge + outer sidewall has damaged (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge + outer sidewall has damaged (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened worn on inner face (1.1.14 (a) (ii))**MOT #5**

2020-10-30 13:23

MOT test number

410671579965

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened worn (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Tyre slightly damaged both front tyres outer sidewall damaged (5.2.3 (d) (ii))**MOT #4**

2020-10-28 10:28

MOT test number

281759778473

Result

✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Tyre slightly damaged both front tyres outer sidewall damaged (5.2.3 (d) (ii))**Advice** Nearside Front Nail in tyre**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt insecure (2.1.3 (g) (ii))

**MOT #3** 2019-10-18 10:58**MOT test number** 558172335049**Result** ✓ Passed**MOT #2** 2019-10-14 14:18**MOT test number** 228220750530**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #1** 2018-10-31 10:38**MOT test number** 155256740078**Result** ✓ Passed**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
19 February 2025

Tax status	Valid until 1 June
Days left	34
MOT expiry date	19 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EJ65FZE
Plate since	2019-09-28
Current registration	EJ65FZE
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2015-10-30
Last registration	2024-02-19
Complete history	See info



Registration #1	2015-10-30	13 mi
Registration #2	2018-10-31	12.017 mi
Registration #3	2019-10-14	19.861 mi
Registration #4	2019-10-18	19.941 mi
Registration #5	2020-10-28	26.432 mi
Registration #6	2020-10-30	26.474 mi
Registration #7	2020-10-30	26.517 mi
Registration #8	2020-10-30	26.559 mi
Registration #9	2021-06-17	30.309 mi
Registration #10	2021-10-28	30.351 mi
Registration #11	2021-10-28	30.393 mi
Registration #12	2021-10-28	30.435 mi
Registration #13	2021-10-28	30.477 mi
Registration #14	2021-10-28	30.519 mi
Registration #15	2021-10-28	30.561 mi
Registration #16	2021-10-28	30.603 mi
Registration #17	2021-10-28	30.645 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1675 mm
Length	4700 mm
Wheel base	2700 mm
Kerb weight	2003 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	D4HBFU265168