



report date: 2024-03-29

## General information

|                     |                                 |
|---------------------|---------------------------------|
| Make                | VOLVO                           |
| Model               | XC90 D5 POWERPULSE R-DESIGN AWD |
| Colour              | White                           |
| Year of manufacture | 2017                            |
| Top speed           | 137 mph                         |
| 0 - 60 mph          | 7.4 seconds                     |
| Gearbox             | 8 speed automatic               |

## Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 231 BHP             |
| Max. torque             | 480 Nm at 1.750 rpm |
| Engine capacity         | 1.969 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 45.6 mpg            |
| Consumption extra urban | 52.3 mpg            |
| Consumption combined    | 49.6 mpg            |
| CO2 emission            | 149 g/km            |
| CO2 label               | F                   |





Internet history

Entry 2

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-09-25                  |
| Pictures      | 11                          |
| Listing price | <a href="#">View report</a> |



source: [cargurus.co.uk](https://cargurus.co.uk)

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-06-14                  |
| Pictures      | 49                          |
| Listing price | <a href="#">View report</a> |



source: [yesauto.com](https://yesauto.com)



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-10-04 |
| MOT pass rate      | 80 %       |
| MOT passed         | 4          |
| Failed MOT tests   | 1          |
| Total advice items | 13         |
| Total items failed | 2          |

## MOT #5 2023-10-05 11:11

MOT test number 204319383304

Result ✓ Passed

Next expiry date 2024-10-04

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened STRONG ADVICE (1.1.14 (a) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear LIGHT UNIT LAMP LENS DAMAGED
- Advice** Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords EDGE (5.2.3 (d) (i))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened STRONG ADVICE (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin BOTH REARS (1.1.13 (a) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

## MOT #4 2022-09-22 11:36

MOT test number 579243123703

Result ✓ Passed

**MOT #3** 2021-09-23 14:27**MOT test number** 360739029429**Result** ✓ Passed**MOT #2** 2020-11-10 12:55**MOT test number** 560735958789**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Covers fitted to engine and under car obscuring view of some testable items**MOT #1** 2020-11-05 13:04**MOT test number** 138707263452**Result** ✗ Failed**Advice** Covers fitted to engine and under car obscuring view of some testable items**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords on tread (5.2.3 (d) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
4 October 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 December          |
| <b>Days left</b>        | 216                             |
| <b>MOT expiry date</b>  | 4 October 2024                  |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|   |            |
|---|------------|
| <b>Vehicle class</b>  | 49         |
| <b>Band</b>   | H          |
| <b>First licence fee (12 months)</b>                        | £ 255,00,- |
| <b>First licence fee diesel non RDE2 tested (12 months)</b> | £ 645,00,- |
| <b>Standard rate (12 months)</b>                            | £ 180,00,- |
| <b>Standard rate (6 months)</b>                             | £ 99,00,-  |
| <b>Premium rate (12 months)</b>                             | £ 570,00,- |
| <b>Premium rate (6 months)</b>                              | £ 313,50,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,299 |
| Auction value               | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |            |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

|                      |                |
|----------------------|----------------|
| Number of plates     | 1              |
| Current registration | <b>YP67VMK</b> |
| Plate since          | 2024-03-29     |
| Current registration | <b>YP67VMK</b> |
| Plate since          | 2024-03-29     |

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 8                        |
| First mileage registration | 2017-11-04               |
| Last registration          | 2023-10-05               |
| Complete history           | <a href="#">See info</a> |



|                 |            |           |
|-----------------|------------|-----------|
| Registration #1 | 2017-11-04 | 23 mi     |
| Registration #2 | 2020-11-05 | 27.962 mi |
| Registration #3 | 2020-11-10 | 28.030 mi |
| Registration #4 | 2020-11-10 | 28.030 mi |
| Registration #5 | 2020-11-10 | 28.030 mi |
| Registration #6 | 2020-11-10 | 28.030 mi |
| Registration #7 | 2020-11-10 | 28.030 mi |
| Registration #8 | 2020-11-10 | 28.030 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 97%                             |
| Children       | 87%                             |
| Pedestrian     | 72%                             |
| Safety systems | 94%                             |
| Overall rating | 89%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 2008 mm |
| Height              | 1776 mm |
| Length              | 4950 mm |
| Wheel base          | 2984 mm |
| Kerb weight         | 2009 kg |
| Max. allowed weight | 2750 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 71 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 7                |

|                        |         |
|------------------------|---------|
| <b>Number of axles</b> | 2       |
| <b>Engine number</b>   | 2179205 |