





report date: 2024-03-29

#### General information

Make	ТОУОТА
Model	RAV-4 GT T-BAR COUPE
Colour	Red
Year of manufacture	1997
Top speed	137 mph
0 - 60 mph	7.7 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	168 BHP
Max. torque	185 Nm at 4.800 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol



CarCheck.co.uk page 1/16



report date: 2024-03-29

### Internet history

#### Entry 1

Date 2021-08-15

Pictures 9

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/16



report date: 2024-03-29

### **MOT** history

MOT expiry date	2021-12-03
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	74
Total items failed	13

MOT #22		2020-11-30 16:03
MOT test	number	986871445660
Result		✓ Passed
Next expi	ry date	2021-12-03
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (	c))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.13	1 (c))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11	. (c))
Advice	Central Front Exhaust mounting defective (6.1.2 (a))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11	(c))

CarCheck.co.uk page 3/16



report date: 2024-03-29

**MOT #21** 2020-11-26 15:58

**MOT test number** 212133042446

Result X Failed

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Central Front Exhaust mounting defective (6.1.2 (a))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Central Rear Brake pipe excessively corroded @ rear o/s (1.1.11 (c))

MOT #20 2019-11-29 13:32

MOT test number 671971813364

Result 

Passed

Advice Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #19** 2019-11-29 13:32

MOT test number 703637163714

Result X Failed

**Pass with rectification** Rear Registration plate does not conform to the specified requirements (0.1 (d))

**Pass with rectification** Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Advice Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**Pass with rectification** Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Advice Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

CarCheck.co.uk page 4/16



report date: 2024-03-29

**MOT #18** 2018-12-04 15:59 694612494618 **MOT** test number ✓ Passed Result Minor Nearside Rear Stop lamp(s) lens defective which has no effect on emitted light (4.3.1 (b) (i)) **Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a)) **Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) Advice Exhaust system deteriorated Advice Offside Rear Brake pipe corroded, covered in grease or other material To flexi (1.1.11 (c))

**MOT #17** 2018-12-04 15:28 **MOT test number** 213866900049 Result × Failed **Advice** Exhaust system deteriorated **Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a)) Fail Rear Registration plate missing (0.1 (a)) **Minor** Nearside Rear Stop lamp(s) lens defective which has no effect on emitted light (4.3.1 (b) (i)) **Advice** Offside Rear Brake pipe corroded, covered in grease or other material To flexi (1.1.11 (c))

CarCheck.co.uk page 5/16



report date: 2024-03-29

MOT #16 2018-07-31 09:27

MOT test number 646100266656

✓ Passed Result **Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Central Rear Brake pipe corroded, covered in grease or other material o/s (1.1.11 (c)) Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Offside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive spring mounting (5.3.6 (a) (i)) Advice Brake cable mountings to back plates corroding Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Nearside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive spring mounting (5.3.6 (a) (i)) **Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

CarCheck.co.uk page 6/16



report date: 2024-03-29

**MOT #15** 2018-07-31 09:27

**MOT test number** 317998169997

Result X Failed

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively fitted 20" wiper blade (3.4 (b) (ii))

**Advice** Nearside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive spring mounting (5.3.6 (a) (i))

**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Central Rear Brake pipe corroded, covered in grease or other material o/s (1.1.11 (c))

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Pass with rectification Offside Stop lamp(s) not working fitted new 12/21 5w bulb (4.3.1 (a) (ii))

**Advice** Offside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive spring mounting (5.3.6 (a) (i))

**Advice** Brake cable mountings to back plates corroding

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14 2017-08-02 16:12

MOT test number 658426676134

Result \( \sqrt{Passed} \)

**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice N/s and o/s hand brake mountings to back plates corroded cables deteriorating

**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Central Rear Brake pipe slightly corroded o/s (3.6.B.2c)

**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

CarCheck.co.uk page 7/16



report date: 2024-03-29

**MOT #13** 2017-08-02 09:05 745563747347 **MOT** test number Result × Failed **Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c) Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) Fail Nearside Fuel tank insecure strap corroded (7.2.1) Advice Offside Front Brake pipe slightly corroded (3.6.B.2c) **Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c) Fail Nearside Front position lamp(s) not working (1.1.A.3b) Nearside Front Brake pipe slightly corroded (3.6.B.2c) **Advice** Advice N/s and o/s hand brake mountings to back plates corroded cables deteriorating **Advice** Central Rear Brake pipe slightly corroded o/s (3.6.B.2c)

MOT #12		2016-08-09 09:06
MOT test	number	897101302597
Result		✓ Passed
Advice	Centre Rear Brake pipe slightly corroded o/s (3.6.B.2c)	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Oil leak	
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Front Exhaust has a minor leak of exhaust gases small hole (7.1.2)	

CarCheck.co.uk page 8/16



report date: 2024-03-29

MOT #11		2015-08-11 11:43
MOT test	number	498213225260
Result		✓ Passed
Advice	Centre Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)	

MOT #10		2014-08-06 09:05
MOT test	number	898808114287
Result		✓ Passed
Advice	Centre Rear Brake pipe slightly corroded (3.6.B.2c)	
Notice	O/s front tyres worn on inner edge/perishing.	
Advice	Offside Front constant velocity joint is slightly worn (2.5.C.1b)	
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Notice	N/s front tyre has side wall damage.	
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	

MOT #9	2013-08-07 11:30
MOT test number	656149213234
Result	✓ Passed

CarCheck.co.uk page 9/16



MOT #2

Result

**MOT** test number

# R599VNN

report date: 2024-03-29

2007-08-09 10:54

914001027237

✓ Passed

MOT #8	2012-08-08 12:57
MOT test number	866991222278
Result	✓ Passed
MOT #7	2011-08-04 09:51
MOT test number	436616411242
Result	✓ Passed
MOT #6	2010-08-11 12:33
MOT test number	542983420265
Result	✓ Passed
MOT #5	2009-08-06 15:31
MOT test number	923688119241
Result	✓ Passed
MOT #4	2009-08-06 10:12
MOT test number	300108119283
Result	<b>≍</b> Failed
Fail Nearside Front Ball joint has excessive play (2.2.B.1f)	
MOT #3	2008-08-12 10:48
MOT test number	103605628210
Result	✓ Passed
	v i abbea

CarCheck.co.uk page 10/16



report date: 2024-03-29

MOT #1		2006-08-14 10:10
MOT test	number	833016826209
Result		<b>✓</b> Passed
Advice	Offside Front brake disc slightly pitted (3.5.1h)	
Advice	Nearside Front brake disc slightly pitted (3.5.1h)	

CarCheck.co.uk page 11/16




report date: 2024-03-29

#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-29

$\sim$		
Owner	hictory	7
OWITCE	1113601	1

*	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
***************************************	
manage of the same	
***************************************	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 13/16



report date: 2024-03-29

#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 14/16



report date: 2024-03-29

### Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	1997-09-30
Last registration	2020-11-30
Complete history	See info



7 mi
60.376 mi
65.917 mi
71.228 mi
75.581 mi
75.581 mi
83.284 mi
85.255 mi
88.256 mi
90.962 mi
94.742 mi
94.742 mi 99.546 mi

More info >



report date: 2024-03-29

#### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	<b>★本</b> ★
Video	see crash video



### Additional information

Fuel tank capacity	54
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	3S9337363

CarCheck.co.uk page 16/16