



ST080JM

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TIGUAN ESCAPE TDI
Colour	Blue
Year of manufacture	2008
Top speed	116 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.1 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg
CO2 emission	182 g/km
CO2 label	I







Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-14
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	22
Total items failed	4

MOT #17	2024-03-15 15:26
MOT test number	696403138703
Result	✓ Passed
Next expiry date	2025-03-14

MOT #16	2023-04-26 14:48
MOT test number	560079679805
Result	✓ Passed

MOT #15	2022-07-22 13:19
MOT test number	270211185621
Result	✓ Passed
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

**MOT #14** 2022-07-21 14:22**MOT test number** 529153075814**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))**MOT #13** 2021-07-24 10:53**MOT test number** 821875360176**Result** ✓ Passed**MOT #12** 2019-06-01 08:41**MOT test number** 625311627382**Result** ✓ Passed**MOT #11** 2018-05-29 10:55**MOT test number** 124560560065**Result** ✓ Passed**MOT #10** 2017-05-20 11:18**MOT test number** 917408066036**Result** ✓ Passed

**MOT #9** 2016-06-02 10:11**MOT test number** 140044976740**Result** ✓ Passed**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Centre bearing on propshaft worn**MOT #8** 2016-06-02 10:11**MOT test number** 535088761524**Result** ✗ Failed**Advice** Centre bearing on propshaft worn**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)**MOT #7** 2015-05-04 11:26**MOT test number** 798604325109**Result** ✓ Passed**MOT #6** 2014-03-17 09:29**MOT test number** 137606174469**Result** ✓ Passed**MOT #5** 2013-05-16 11:02**MOT test number** 936516333160**Result** ✓ Passed

**MOT #4** 2013-05-15 14:28**MOT test number** 667045433143**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear coil spring fractured (2.4.C.1a)**MOT #3** 2012-05-16 11:10**MOT test number** 579917332181**Result** ✓ Passed**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Engine oil level low**Notice** Nearside rear shock absorber dust cover loose**Notice** Slight wear on inner edges of rear tyres**MOT #2** 2011-05-27 08:58**MOT test number** 429697141151**Result** ✓ Passed**Notice** Slight pitting at front and rear brake discs**Notice** Rear tyres wearing low**MOT #1** 2011-05-26 10:19**MOT test number** 797966141152**Result** ✗ Failed**Notice** Slight smear from front wiper blades**Notice** Slight pitting at front and rear brake discs**Notice** Rear tyres wearing low**Fail** Offside Rear coil spring incomplete (2.4.C.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
14 March 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	14 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-05-26
Last registration	2024-03-15
Complete history	See info



Registration #1	2008-05-26	18 mi
Registration #2	2011-05-26	37.230 mi
Registration #3	2011-05-27	37.230 mi
Registration #4	2012-05-16	44.991 mi
Registration #5	2013-05-15	52.781 mi
Registration #6	2013-05-16	52.781 mi
Registration #7	2014-03-17	61.249 mi
Registration #8	2015-05-04	71.506 mi
Registration #9	2016-06-02	79.146 mi
Registration #10	2016-06-02	79.146 mi
Registration #11	2016-06-02	79.146 mi
Registration #12	2016-06-02	79.146 mi
Registration #13	2016-06-02	79.146 mi
Registration #14	2016-06-02	79.146 mi
Registration #15	2016-06-02	79.146 mi
Registration #16	2016-06-02	79.146 mi
Registration #17	2016-06-02	79.146 mi
Registration #18	2016-06-02	79.146 mi
Registration #19	2016-06-02	79.146 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1809 mm
Height	1686 mm
Length	4457 mm
Wheel base	2604 mm
Kerb weight	1590 kg
Max. allowed weight	2240 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CBA 049691