





report date: 2024-03-29

## General information

| Make                | MINI              |  |
|---------------------|-------------------|--|
| Model               | PACEMAN COOPER S  |  |
| Colour              | Black             |  |
| Year of manufacture | 2014              |  |
| Top speed           | 130 mph           |  |
| 0 - 60 mph          | 7.9 seconds       |  |
| Gearbox             | 6 speed automatic |  |

## Engine & fuel consumption

| Power                   | 184 BHP             |  |
|-------------------------|---------------------|--|
| Max. torque             | 240 Nm at 1.600 rpm |  |
| Engine capacity         | 1.598 cc            |  |
| Cylinders               | 4                   |  |
| Fuel type               | Petrol              |  |
| Consumption city        | 29.7 mpg            |  |
| Consumption extra urban | 49.6 mpg            |  |
| Consumption combined    | 39.8 mpg            |  |
| CO2 emission            | 157 g/km            |  |
| CO2 label               | G                   |  |



CarCheck.co.uk page 1/12



## Internet history

#### Entry 1

Date 2022-04-15

Pictures 35

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date    | 2025-04-12 |
|--------------------|------------|
| MOT pass rate      | 89 %       |
| MOT passed         | 8          |
| Failed MOT tests   | 1          |
| Total advice items | 14         |
| Total items failed | 1          |

| MOT #9   |  | 2024-04-13 10:09 |
|--|--|------------------|
| MOT test   | number   | 171853925056     |
| Result   |  | ✓ Passed         |
| Next expi  | ry date  | 2025-04-12       |
| Advice   | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |
| Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |  | L.1.14 (a) (ii)) |
| Advice   | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))  |                  |

| MOT #8  |  | 2024-04-13 08:32 |
|---|--|------------------|
| MOT test  | number   | 279587809465     |
| Result  |  | <b>×</b> Failed  |
| <b>Fail</b> No  | earside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))             |                  |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))              |  |                  |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge worn both edges (5.2.3 (e)) |  |                  |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))             |  |                  |
| Advice  | Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.3 | 1.14 (a) (ii))   |

CarCheck.co.uk page 3/12



MOT test number

Result

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Tyre slightly damaged/cracking or perishing 225/45-18 RF (5.2.3 (d) (ii))

MOT test number

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5

MOT test number

484052529706

Result

✓ Passed

MOT #4

2020-03-16 10:05

MOT test number

495815857912

Result

✓ Passed

Advice

Light perishing /cracking /ageing to all tyres

 MOT #3
 2019-03-22 15:27

 MOT test number
 527115239151

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



| MOT #2          | 2018-03-15 14:31 |
|-----------------|------------------|
| MOT test number | 630698321725     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #1          | 2017-03-24 08:44 |
| MOT test number | 939896074177     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 5/12



## Tax & MOT check



| Tax status       | Valid until 1 April |
|------------------|---------------------|
| Days left        | 336                 |
| MOT expiry date  | 12 April 2025       |
| Full MOT history | See MOT history     |

#### Tax calculation

| Vehicle class                           | 48         |
|---|------------|
| Band                                    | G          |
| Single payment (12 months)              | £ 240,00,- |
| Single six month payment                | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



## Owner history

| For how long did the current and previous owner(s) have this MINI? How many owners di<br>Check it in the premium report and see all owner registrations. Download the full report |             |
|---|-------------|
|   |             |
| HARMAN CO.  |             |
|   |             |
|   |             |
|   |             |
| ********  |             |
| ***************************************   |             |
| ***************************************   |             |
|   | More info > |
|   | , , ,       |
| Plate changes   |             |
| See in this check if this MINI had different number plates.   |             |
| Number of plates  | ,           |
| Current registration  | NK SIE      |
| Plate since   |             |
| Current registration  | UK UK       |
| Plate since   |             |
|   | More info > |

CarCheck.co.uk page 9/12



#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

Contact info

More info >

CarCheck.co.uk page 10/12



# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 11         |
| First mileage registration | 2014-03-24 |
| Last registration          | 2024-04-13 |
| Complete history           | See info   |



| Registration #1  | 2014-03-24 | 9 mi      |
|------------------|------------|-----------|
| Registration #2  | 2017-03-24 | 5.237 mi  |
| Registration #3  | 2018-03-15 | 6.498 mi  |
| Registration #4  | 2019-03-22 | 7.496 mi  |
| Registration #5  | 2020-03-16 | 13.264 mi |
| Registration #6  | 2021-03-26 | 20.332 mi |
| Registration #7  |            | 11.777 es |
| Registration #8  |            | 71.777 es |
| Registration #9  |            | 11.777 es |
| Registration #10 |            | 71.777 66 |
| Registration #11 |            | 73.777 au |

More info >

CarCheck.co.uk page 11/12



## Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| 50482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 84%             |
| Children       | 83%             |
| Pedestrian     | 63%             |
| Safety systems | 71%             |
| Overall rating | 78%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1789 mm |
|---------------------|---------|
| Height              | 1561 mm |
| Length              | 4110 mm |
| Wheel base          | 2595 mm |
| Kerb weight         | 1335 kg |
| Max. allowed weight | 1845 kg |

## Additional information

| Fuel tank capacity                | 47 I                  |
|-----------------------------------|-----------------------|
| Fuel delivery                     | Multi-Point Injection |
| Number of doors                   | 5                     |
| Number of seats<br>CarCheck.co.uk | 5 page 12/12          |

Number of axles2Engine numberA563J843