





report date: 2024-03-29

General information

Make	RENAULT
Model	MASTER LM35 BUSINESS ENERGY DCI
Colour	White
Year of manufacture	2017
Gearbox	6 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	340 Nm at 1.500 rpm
Engine capacity	2.298 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	39.2 mpg
CO2 emission	186 g/km
CO2 label	J



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2022-02-24

Pictures 17

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-08-06
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	12
Total items failed	7

MOT #6	2023-08-07 12:10
MOT test number	522215447967
Result	✓ Passed
Next expiry date	2024-08-06

MOT #5		2022-05-17 12:34
MOT test	number	913709439719
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #4	2022-05-09 10:45
MOT test number	350099765105
Result	X Failed
Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))

CarCheck.co.uk page 3/11



Passed

MOT #3 2021-05-04 10:51

MOT test number 798840729068

Result \rightarrow Passed

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #2 2020-04-08 10:03

MOT test number 783571192799

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Rear Nail in tyre

Result

Advice Brake pedal wearing smooth pedal rubber worn (1.1.2 (c))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #1 2020-04-08 09:10

MOT test number 463239948163

Result X Failed

Advice Brake pedal wearing smooth pedal rubber worn (1.1.2 (c))

Fail Nearside Rear reflector defective or damaged by more than 50% of the reflecting surface (4.8.1 (a) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Pass with rectification Headlamp aim too high both sides (4.1.2 (a))

Advice Nearside Rear Nail in tyre

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	6 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
THE STREET STREE	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	NIE NIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-05-05
Last registration	2023-08-07
Complete history	See info



Registration #1	2017-05-05	13 mi
Registration #2	2020-04-08	119.530 mi
Registration #3	2020-04-08	119.530 mi
Registration #4	2021-05-04	124.983 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
50295	
60482	
60501	
60566	
60567	
50569	

Dimensions & weight

Width	2470 mm
Height	2496 mm
Length	6198 mm
Kerb weight	2029 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	6
Number of seats	3
Engine number	C024052

CarCheck.co.uk page 11/11