





report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 HDI ACTIVE
Colour	Blue
Year of manufacture	2011
Top speed	103 mph
0 - 60 mph	16.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.398 сс
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	76.4 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/14



report date: 2024-03-28


Internet history

Entry 1

Date 2021-07-07

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-03-20
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	25
Total items failed	9

MOT #16	2024-03-06 14:21
MOT test number	143674476723
Result	✓ Passed
Next expiry date	2025-03-20

MOT #15	2023-03-15 16:30
MOT test number	463841293019
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #14	2022-03-12 10:43
MOT test number	136491503071
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT test number

278894687913

Result

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

Advice Oil leak on engine

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Both rear Tyres starting to perish

MOT #12		2020-03-19 16:55
MOT test	number	915013340693
Result		✓ Passed
Advice	Offside Rear All direction indicators slightly discoloured (4.4.3 (a))	
Advice	Nearside Rear All direction indicators slightly discoloured (4.4.3 (a))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #11 2020-03-18 10:08 **MOT** test number 605457821596 Result × Failed **Advice** Offside Rear All direction indicators slightly discoloured (4.4.3 (a)) Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Hazard warning switch inoperative (4.4.2 (a) (ii)) Fail **Advice** Nearside Rear All direction indicators slightly discoloured (4.4.3 (a)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #10

MOT test number

Result

Advice Nearside Front Top suspension mounting juddering slightly

2019-03-21 11:53

445366760182

✓ Passed

MOT #9

MOT test number

962418996235

Result

✓ Passed

MOT test number

Result

Pass with rectification

Nearside Front position lamp(s) not working (1.1.A.3b)

Pass with rectification

Nearside Headlamp not working on dipped beam (1.7.5a)

Pass with rectification

Nearside Stop lamp not working (1.2.1b)

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT test number

Result

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #5

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT test number

611343292656

Result

X Failed

Fail Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure out of shape (4.1.D.1b)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #3		2015-05-15 10:21
MOT test number		239755735415
Result		✓ Passed
MOT #2		2014-05-21 08:49
MOT test number		355361144130
Result		✓ Passed
MOT #1		2014-05-21 08:49
MOT test number		275421644139
Result		× Failed
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)	

CarCheck.co.uk page 7/14



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	20 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



faste since

CF110UN

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. ober of plates

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-08-22
Last registration	2024-03-06
Complete history	See info



Registration #1	2011-08-22	9 mi
Registration #2	2014-05-21	46.034 mi
Registration #3	2015-05-15	53.084 mi
Registration #4	2016-05-16	71.169 mi
Registration #5	2016-05-16	71.169 mi
Registration #6	2017-05-08	79.423 mi
Registration #7	2017-05-08	79.423 mi
Registration #8	2018-05-04	85.488 mi
Registration #9	2018-05-04	85.488 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 mi
Registration #14		11.777 es
Registration #15		9.77 es
Registration #16		11.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1972 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1273 kg
Max. allowed weight	1665 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 14/14

Number of axles 2

Engine number FDBV0147325