




report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 D5 SE LUX AWD
Colour	Black
Year of manufacture	2012
Top speed	127 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	200 BHP
Max. torque	420 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.5 mpg
CO2 emission	219 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-07-16
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	3
Total items failed	9

MOT #12	2023-07-17 14:25
MOT test number	993737289782
Result	✓ Passed
Next expiry date	2024-07-16
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11	2023-07-04 11:13
MOT test number	831603558618
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Offside Rear fog lamp not working (4.5.1 (a) (ii))

MOT #10	2022-07-02 08:23
MOT test number	433325891220
Result	✓ Passed

MOT #9	2021-07-05 10:32
MOT test number	352925694656
Result	✓ Passed
Advice	Rear Tyre worn close to legal limit/worn on edge BOTH ON OUTER EDGES 235/60/18 (5.2.3 (e))

**MOT #8** 2020-06-19 11:06**MOT test number** 132916557438**Result** ✓ Passed**MOT #7** 2020-06-18 11:12**MOT test number** 878986992839**Result** ✗ Failed

- Fail** Nearside Windscreen washer not working (3.5 (a))
- Fail** Central Rear Seat belt retracting mechanism defective (7.1.2 (e))
- Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Windscreen washer not working (3.5 (a))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #6 2019-08-29 09:10**MOT test number** 647589810264**Result** ✓ Passed**MOT #5** 2018-08-21 09:14**MOT test number** 970096426124**Result** ✓ Passed**MOT #4** 2017-08-21 09:08**MOT test number** 992845514179**Result** ✓ Passed**MOT #3** 2016-08-11 11:59**MOT test number** 764041770341**Result** ✓ Passed



MOT #2	2016-08-11 09:27
MOT test number	696094440026
Result	✗ Failed
Fail	Offside Rear fog lamp not working (1.3.2b)
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1	2015-08-12 13:17
MOT test number	953062214501
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
16 July 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	16 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	AF62LYR
Plate since	2024-03-29
Current registration	AF62LYR
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-01
Last registration	2023-07-17
Complete history	See info



Registration #1	2012-09-01	7 mi
Registration #2	2015-08-12	20.746 mi
Registration #3	2016-08-11	29.424 mi
Registration #4	2016-08-11	29.426 mi
Registration #5	2017-08-21	33.659 mi
Registration #6	2018-08-21	39.506 mi
Registration #7	2019-08-29	42.877 mi
Registration #8	2020-08-29	45.277 mi
Registration #9	2021-08-29	47.677 mi
Registration #10	2022-08-29	49.077 mi
Registration #11	2023-08-29	50.477 mi
Registration #12	2024-08-29	51.877 mi
Registration #13	2025-08-29	53.277 mi
Registration #14	2026-08-29	54.677 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2112 mm
Height	1784 mm
Length	4807 mm
Wheel base	2857 mm
Kerb weight	2158 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1139303