





report date: 2024-03-29

General information

Make	BMW
Model	7 SERIES 745I
Colour	White
Year of manufacture	2004
Top speed	155 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	329 BHP	
Max. torque	450 Nm at 3.600 rpm	
Engine capacity	4.399 сс	
Cylinders	8	
Fuel type	Gas / Bi-fuel	
Consumption city	18.2 mpg	
Consumption extra urban	34.0 mpg	
Consumption combined	25.9 mpg	



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-01-29

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

	~		
10/1/	1	hic	tory
- 1010	,, ,	1115	IUIV
	<i>-</i> .		

MOT expiry date	2024-11-21
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	2
Total items failed	9

MOT #7	2023-11-22 10:15
MOT test number	538419982393
Result	✓ Passed
Next expiry date	2024-11-21

MOT #	6	2023-11-09 11:12
MOT te	est number	906142482529
Result		🗙 Failed
Fail	Offside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))	
Fail (ii))	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingre-	ss of dirt (5.3.4 (b)
Fail	Offside Rear Road wheel fractured (5.2.2 (a))	
Fail	Offside Rear Tyre has a lump, caused by separation or partial failure of its structure	e (5.2.3 (d) (ii))
Fail (b) (ii))	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingi	ress of dirt (5.3.4
Fail	Offside Rear Tyre has a lump, caused by separation or partial failure of its structure	e (5.2.3 (d) (ii))

MOT #5		2022-11-11 13:15
MOT test	number	863242797837
Result		✓ Passed
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4 2021-03-08 13:07

MOT test number 278463957616

MOT #3 2021-02-24 08:18

MOT test number 871880841360

Result X Failed

Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail Nearside Front Road wheel fixing missing (5.2.1 (a) (i))

MOT #2 2020-03-10 13:41

MOT test number 376633666921

Result ✓ Passed

MOT #1 2019-02-27 16:05

MOT test number 136056218015

Result \rightarrow Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

See MOT history

Tax & MOT check

Full MOT history



Tax statusValid until 1 AprilDays left338MOT expiry date21 November 2024

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

_			
Owne	≥r h	ıct	orv
	- 1	IJĿ	oi v

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have?		
Check it in the premium report and see all owner registrations. Download the full report	<u>nere</u> .	

	More info	
	More inio	
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	NK NK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2004-08-01
Last registration	2023-11-22
Complete history	See info



Registration #1	2004-08-01	20 mi
Registration #2	2019-02-27	46.571 mi
Registration #3	2020-03-10	50.750 mi
Registration #4		11.777 es
Registration #5	2021-02-24	51.036 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
50569	

Dimensions & weight

Width	2133 mm
Height	1492 mm
Length	5029 mm
Wheel base	2990 mm
Kerb weight	1870 kg

Additional information

Fuel tank capacity	88 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	N62B44A

CarCheck.co.uk page 11/11